

Product Phased-Out Notice

Last Update: 9/7/2016

PAPS formally announce that we have phased out following products. This announcement will take effect immediately. Please review this phase-out notice carefully and contact your regional PAPS buyer immediately if your customers have any further inquiries on these items.

Phase Out Reason

The manufacturer has decided to phase out the product as production is not economically viable.

Milestone	Definition	Date
Phase Out Date (EOL):	Date that this announcement takes effective	2016/9/7
Last Time Buy (LTB):	Last date for sales to submit order request to PAPS buyer.	2016/11/30

Phased-out Products in This Announcement

Part Number	Product Description	MPN	Replacement Model
96MPCM-1.8F5-1M4T	CELERON M 1.86G 533F 1M 478P 440(G)	LF80538NE0361M E (440)	N/A
96MPCM-2.0F5-1M4T1	CELERON M 2.0G 533F 1M 478P 550(G)	LF80537NE0411M (550/SLAJ9)	N/A
96MPCM-2.0F6-1M4T	CELERON M 2.0G 667F 1M 478P 575(G)	LF80537NF0411M (575)	N/A
96MPCD-3.2F5-5K7T	CELERON D 3.2G 533F 512K 775P 352(G)	HH80552RE08851 2(352)	N/A

96MPCL-2.2F8-5K7T	CELERON 2.2G 800F 512K 775P E1500(G)	HH80557PG049D (E1500/SLAQZ)	N/A
96MPC4-2.0F8-5K7T	CELERON 2.0G 800F 512K 775P 440(G)	HH80557RG04151 2 (440) / SL9XL	N/A
96MPP4-3.4F8-2M7T1	PENTIUM 4 3.4G 800F 2M 775P 651(G)	HH80552PG0962M (651)	N/A
96MPPD-1.8F8-1M7T	PENTIUM 1.8G 800F 1M 775P E2160(G)	HH80557PG0331M (E2160) / SLA8Z	N/A
96MPDM-20F6-2M4T	CORE DUO 2.0G 667F 2M 478P T2500(G)	LF80539GF0412M(T2500) SL8VP / SL9EH	N/A
96MP2DD-18F8-2M7T	CORE2 DUO DT 1.8G 800F 2M 775P E4300(G)	HH80557PG0332M (E4300) -- Embedded	N/A
96MP2DD-21FA-2M7T	CORE2 DUO DT 2.13G 1KF 2M 775P E6400(G)	HH80557PH0462M (E6400/SLA97) Embedded	N/A
96MP2DM-21F6-4M4T	CORE2 DUO M 2.16G 667F 4M 478P T7400(G)	LF80537GF0484M (T7400) / SL9SE / SLGFJ)	N/A
96MP2DM-22GF8-4M4T	CORE2 DUO M 2.2G 800F 4M 478P T7500(G)	LF80537GG0494M (T7500) /SLAFB	N/A