



520 Park East Blvd., New Albany, IN 47150 U.S.A  
(812)-944-6733 / 1-800-SAMTEC9

## Product Change Notification

1. ECN #: 243782

2. Date of Announcement: February 24, 2015

### 3. Series:

- TFM - .050 X .050 MICRO STRIPS
- TFML - .050 SHROUDED TERMINAL

### 4. Part #'s Affected

- TFM-1XX-XX-XXX-D-XXX
- TFM-1XX-XX-X-S-XX
- TFM-1XX-XX-X-S-RA
- TFML-1XX-XX-XXX-D-XXX

### 5. Description of Change:


ADDED LONGITUDINAL COIN TO ONE SIDE OF TAIL TO AID STRAIGHTNESS

### 6. Method of Identifying Change


CUSTOMER CAN SEE WHAT APPEARS TO BE A SCRIBE LINE DOWN THE LENGTH OF THE TAIL ON ONE SIDE



EXISTING PIN WITHOUT COIN



REVISED PIN



TFM ASSEMBLY WITH "TAIL WITH" AND "TAIL WITHOUT" COIN

**7. Reason for Change:**

COINING KEEPS THE TAIL STRAIGHTER, THIS IS A DESIGN IMPROVEMENT AND IS BEING IMPLEMENTED AS A RUNNING CHANGE, THERE COULD BE MIXED GENERATION PINS WITHIN THE SAME PART AND SHIPMENTS COULD ALTERNATE FROM EXISTING TO REVISED AND BACK TO EXISTING DEPENDING ON INVENTORY LEVELS OF THE SPECIFIC PINS INVOLVED.

**8. Impact of Change on Form, Fit, or Function:**

- Form - no impact on form, fit or function other than visible

**9. Projected Implementation Date:** March 16, 2015