
PRODUCT CHANGE NOTIFICATION NO: E-14-004896
PCN DATE: 10-APR-14

We would like to inform you about the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

GENERAL PRODUCT DESCRIPTION:

Revise Customer drawing of 330249(JAM NUT)

DESCRIPTION OF CHANGE:

Correct a drafting Error on Thread dimension for the TE part number 2-330249-2

REASON FOR CHANGE:

Document Clarification. TE customer print 330249 called out part number 2-330249-2 has a 3/8-24UNEF-2B thread, it is a drafting error,it should 3/8-32UNEF-2B thread,

ESTIMATE DATE:

LAST ORDER DATE:

(OBSOLETE PARTS ONLY)

LAST SHIP DATE:

(OBSOLETE PARTS ONLY)

FIRST DATE TO SHIP CHANGED PARTS:

(CHANGED PARTS ONLY)

**LAST DATE FOR MIXED
SHIPMENTS:**

(CHANGED PARTS ONLY)

PRODUCT CHANGE NOTIFICATION NO: E-14-004896
PCN DATE: 10-APR-14

DOCUMENTATION BEING MODIFIED

Customer Drawing
330249

TE CONNECTIVITY

PRODUCT CHANGE
NOTIFICATION

PRODUCT CHANGE NOTIFICATION NO: E-14-004896
PCN DATE: 10-APR-14

We would like to inform you about the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

GENERAL PRODUCT DESCRIPTION:

Revise Customer drawing of 330249(JAM NUT)

DESCRIPTION OF CHANGE:

Correct a drafting Error on Thread dimension for the TE part number 2-330249-2

REASON FOR CHANGE:

Document Clarification. TE customer print 330249 called out part number 2-330249-2 has a 3/8-24UNEF-2B thread, it is a drafting error, it should 3/8-32UNEF-2B thread,

TE CONNECTIVITY

PRODUCT CHANGE
NOTIFICATION

PRODUCT CHANGE NOTIFICATION NO: E-14-004896
PCN DATE: 10-APR-14

The documents listed below are being modified. Related parts that are not explicitly listed on this PCN are not being modified or discontinued per the PCN. The Last Order Date, Last Ship Date, First Date to Ship Changed Parts, and Last Date for Mixed Shipments apply only to parts explicitly on this PCN under 'PARTS BEING MODIFIED' or 'Parts being Discontinued or available with Alternates heading' (if any).

DOCUMENTATION BEING MODIFIED	CUSTOMER SPECIFIC PARTS WITHIN THE DOCUMENT	DOCUMENTATION REVISIONS
Customer Drawing 330249	1-330249-1	Old Revision: H1

TE CONNECTIVITY

PRODUCT CHANGE
NOTIFICATION

PRODUCT CHANGE NOTIFICATION NO: E-14-004896
PCN DATE: 10-APR-14

We would like to inform you about the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

GENERAL PRODUCT DESCRIPTION:

Revise Customer drawing of 330249(JAM NUT)

DESCRIPTION OF CHANGE:

Correct a drafting Error on Thread dimension for the TE part number 2-330249-2

REASON FOR CHANGE:

Document Clarification. TE customer print 330249 called out part number 2-330249-2 has a 3/8-24UNEF-2B thread, it is a drafting error, it should 3/8-32UNEF-2B thread,

TE CONNECTIVITY

PRODUCT CHANGE
NOTIFICATION

PRODUCT CHANGE NOTIFICATION NO: E-14-004896
PCN DATE: 10-APR-14

The documents listed below are being modified. Related parts that are not explicitly listed on this PCN are not being modified or discontinued per the PCN. The Last Order Date, Last Ship Date, First Date to Ship Changed Parts, and Last Date for Mixed Shipments apply only to parts explicitly on this PCN under 'PARTS BEING MODIFIED' or 'Parts being Discontinued or available with Alternates heading' (if any).

DOCUMENTATION BEING MODIFIED

CUSTOMER SPECIFIC PARTS
WITHIN THE DOCUMENT

DOCUMENTATION REVISIONS

Customer Drawing
330249

1-330249-1

Old Revision: H1