

# PRODUCT CHANGE NOTIFICATION

## MAGNETICS

### Bourns® Model 8101-RC, 8102-RC and 8103-RC Common Mode Chokes

#### Marking Process Change

#### Change from Ink Marking to Laser Etching

Riverside, California – October 1, 2020 – Effective March 20, 2021, Bourns will change the marking process for the Model [8101-RC](#), [8102-RC](#) and [8103-RC](#) Common Mode Chokes from ink stamping to laser etching. The new process should enhance productivity and improve marking durability.

Current Ink Marking

New Laser Etching



A list of affected part numbers is shown below.

Affected Part Numbers		
8101-RC	8102-RC	8103-RC

The laser marking will have no impact on the fit or function of the product. The form of the product will change due to the appearance of the marking process. The quality and reliability of the marking should be improved as the result of the process change.

*Users should verify that the described changes will not impact the performance of the product in their specific applications.*

IC2091

Implementation dates are as follows:

Date that manufacturing of existing products will cease: **March 20, 2021**

Date that deliveries of modified products will begin: **March 21, 2021**

First date code using the above changes: **2112**

If you have any questions or need additional information, please feel free to contact [Customer Service/Inside Sales](#).