

PRODUCT DISCONTINUATION



PD_059_10

Important note:

Devices with **E6xxx** in the product name (see below in black letters) are already discontinued with PCN 2009-122. LOD: 2011-03-31 - LDD: 2011-09-30
 Devices with **H6xxx** in the product name (see below in blue letters).

Device E6xxx	Ordering Code	Replacement Device H6xxx	Device E6xxx	Ordering Code	Replacement Device H6xxx
BAV 99W E6327	SP000010340	BAV 99W H6327	BC 807-40W E6433	SP000014689	BC 807-40W H6433
BAV 99W E6433	SP000010341	BAV 99W H6433	BC 808-25W E6327	SP000014777	BC 808-25W H6327
BAW 56W E6327	SP000014991	BAW 56W H6327	BC 808-40W E6327	SP000010462	BC 808-40W H6327
BC 807-16W E6327	SP000014778	BC 807-16W H6327	BC 846BW E6327	SP000010523	BC 846BW H6327
BC 807-25W E6327	SP000014779	BC 807-25W H6327	BC 856BW E6327	SP000012943	BC 856BW H6327
BC 807-40W E6327	SP000014688	BC 807-40W H6327	BC 856BW E6433	SP000012945	BC 856BW H6433

DISCONTINUED			REMARK	NEW (REPLACEMENT)		
Device H6xxx	Ordering Code	Package		Device	Ordering Code	Package
BAV 99W H6327	SP000754054	PG-SOT323-3	Devices with H6xxx in the product name are replacement products in PCN 2009-122 but will not go into volume production and are also discontinued. Last order: 2011-03-31 Last delivery: 2011-09-30	none		
BAV 99W H6433	SP000754058	PG-SOT323-3				
BAW 56W H6327	SP000754066	PG-SOT323-3				
BC 807-16W H6327	SP000745926	PG-SOT323-3				
BC 807-25W H6327	SP000745928	PG-SOT323-3				
BC 807-40W H6327	SP000745930	PG-SOT323-3				
BC 807-40W H6433	SP000746842	PG-SOT323-3				
BC 808-25W H6327	SP000746844	PG-SOT323-3				
BC 808-40W H6327	SP000746846	PG-SOT323-3				
BC 846BW H6327	SP000746854	PG-SOT323-3				
BC 856BW H6327	SP000747442	PG-SOT323-3				
BC 856BW H6433	SP000747444	PG-SOT323-3				

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!