

Light is OSRAM


Not For New Designs OS-NFND-2018-006

17-Jul-2018

Expected discontinuation date: 1-5 Years

Reason: The following products have reached their end of life.

OSRAM OS Expectations: Please use our recommended replacement for new designs. If they may not fit, please contact your local sales office for other solutions. Additionally we ask you to switch for running project as soon as possible to the proposed replacement. Anyway please check your demand and feedback your requested lifetime of these products.
Attention: Q# already announced to be in phase-out process will not be impacted. Dates published in corresponding PDN will be kept.



Please direct your feedback to your local Sales office.

Not for new design products

Recommended Replacement

Not for new design products		Recommended Replacement			
Device	Brand	Device	Brand	Datasheet Ordering Code	Expected PDN start
LUW CN7N	OSLON MX ECE	KW DMLQ31.SG KW DMLS31.SG KW CELNM1.TG LUW CEUN.CE	SYNIOS P2720 OSLON Compact PL OSLON Compact CM	Q65112A3958 Q65112A5690 Q65112A1576 Q65111A1872	Q1 2020
LUW CN7M	OSLON SX	KW DMLN31.SG LUW CRBP	SYNIOS P2720 OSLON Signal	Q65111A6228 Q65111A5182	Q1 2020
LD CN5M	OSLON SX	KB DMLN31.13 LB CRBP	SYNIOS P2720 OSLON Signal	Q65112A0079 Q65112A1994	Q1 2020
LRTB GRUG	DISPLIX Black	KRTB HFLP71.32	DISPLIX P2828	Q65112A3525	Q1 2020