			🗸 Аррі	roved		Rejected
Engineering Change Notice						
ECN Number:		Originator:		Origir	Origination Date:	
2064x		KR			12/21/2020	
Release Level:	Productio	n Product	Number(s):			
	Deviation	12616-06				
Change Type:	SOM		Design		Cost Savings	
	Process		Document	$\checkmark$	Vendor	
Reason for Change:						
Improve FLP quality.						
Change Description:						
The supplier for a component in the film has changed. The film component from the new supplier is the same material but is thicker, resulting in a slight increase in overall product thickness. Testing has shown this change to minimally impact FLP environmental and optical performance.						
Products Affected:						
Previous				Ν	lew	
12616-06_T2			12616-06_T3			