

GLOBAL CUSTOMER PCN NOTIFICATION

PCN Number: CO109579

a pei group						
PCN Notification Date	10/02/2021					
Submitter's Name	Anton Micuda					
Submitter's Contact Details	Anton.Micuda@psbel.com; tech.support@psbel.com					
PCN Number	CO109579					
Description of Change	 New FW version TCP3500-1048G.F1.02.02.08 for models TCP3500-1048G and TCP3500-H048G. New PCB of Control Board for all models of TCP3500 series and related BOM update. Update Test Instruction TCP3500-1048G.TI: Changing Default Factory Settings of models TCP3500-1048G and TCP3500-H048G. Output Voltage will be enabled by Software at Factory Settings New Top cover for models TCP3500-1048G and TCP3500-H048G. 					
Reason for Change	 New Fw version: Improvements from models TCP3500-1024G and TCP4000-H090 New PCB of Control Board and related Hardware changes: Improvements from models TCP3500-1024G and TCP4000-H090 (according Component Derating report) Update Test Instruction: Default Factory Settings was Output Voltage dissabled by Software and new customer needs to use RS485 communication to enable Output Voltage. New Top Cover is improvements from models TCP3500-1024G and TCP3500-1024G and TCP3500-1024G and TCP4000-H090 (EMC improvements) 					
Summary of Changes Between New and Old Part	Some PCBs and mechanical components are shared with all TCP's models. Those changes are improvements from another models: TCP3500-1024G and TCP4000-H090.					
Traceability Guidelines (lot code/date code, markings, ship date)	Revision of all Finish Goods will be changed.					
Last Time Buy Date	N/A					
Datasheet	https://www.belfuse.com/resources/datasheets/powersolutions/ds-bps-tcp3500-series.pdf					
Qualification/Test Data	New Fw 2.2.08 and some Hardware changes have been tested by CR-000132.					
Impact on Reliability	These changes improve reliability - improvements from Component Derating report.					
Bel Power Solutions Old	PN or Process	Bel Power Solutions New PN or Process				
TCP3500-1048S101G revision A		TCP3500-1048S101G revision B				
TCP3500-1048G revision A		TCP3500-1048G revision B				
TCP3500-H048G revision A		TCP3500-H048G revision B				
TCP3500-1048S368G revision A		TCP3500-1048S368G revision B				
CP3500-1048S545G revision 2		TCP3500-1048S545G revision 3				