

## PRODUCT DISCONTINUATION

PD-ION-6U70-16

Business Unit	Product Line Code	Type of Change	Action	Date of issue
ION	CNC 6	Discontinuation	Notify Distributors and Field	1/4/16

*Phoenix Contact's factory has announced the following product(s) is going to be discontinued. Existing specifications will be met or exceeded. Technical support of the discontinued product will continue, as required. Please review and acknowledge this document and take the appropriate action with respect to your existing inventory and ordering replacement parts.*

### Reason for Discontinuation:

The following part numbers have reached end of life.

2867089 - RAD-ISM-900-SET-BD-BUS  
 2867270 - RAD-ISM-900-SET-BD-BUS-ANT  
 2867092 - RAD-ISM-900-BD-BUS  
 2902755 - RAD-ISM-900-SET-XD-REP  
 2902756 - RAD-ISM-900-SET-XD-BUS-2  
 2867539 - RAD-ISM-900-HOP-US  
 2900184 - RAD-ISM-900-XD-HOPKEY  
 5605715-XXXXX - RAD-ISM-900-XD-SET 1-8  
 2885605 - RAD-ISM-900-XD-BUS  
 2867555 - RAD-ISM-900-RS232-BD  
 2867131 - RAD-ISM-900-DATA-BD  
 2867296 - RAD-ISM-900-DATA-BD-BUS  
 2902277 - RAD-ISM-900-DATA-BD-PLUS

For new system requests for the above parts, the Radioline wireless platform should be offered. A chart showing the needed items to have an equivalent system from the discontinued parts is below.

Orders for the discontinued parts will accepted until June 1, 2016.

If you have a specific need for these parts, either for an upcoming project or existing customer, please discuss it with your local Phoenix Contact sales person so we can accommodate your needs the best we can.

**\*\*\*Important – The above part numbers are not compatible with the replacement Radioline product line. If you need assistance in choosing a replacement product, or have general questions on the discontinuations, please contact Technical Service at 800 322-3225.**

## PRODUCT DISCONTINUATION

Warranty Information:
All standard and extended warranty terms will be covered. Support of the discontinued products will be available for all installations.

Stock Status
Can existing stock still be used? Y
Is mixture of stock acceptable? Y

Transaction Dates:
Last Buy from Phoenix Contact: June 1, 2016
Last Scheduled Ship from Phoenix Contact: Available until stock reaches 0

Discontinued Part#	Type Description	Replacement Part#	Type Description
2867089	RAD-ISM-900-SET-BD-BUS	Qty 2 – 2901540 Qty 2 – 2901533 Qty 1 – 2702122	RAD-IFS-900 RAD-DAIO6-IFS RAD-900-CONF-RF1
2867270	RAD-ISM-900-SET-BD-BUS-ANT	Qty 2 – 2901540 Qty 2 – 2901533 Qty 2 – 2904801 Qty 1 – 2702122	RAD-IFS-900 RAD-DAIO6-IFS RAD-900-ANT-OMNI-2-2-RSMA RAD-900-CONF-RF1
2867092	RAD-ISM-900-BD-BUS	2901540	RAD-IFS-900
2902755	RAD-ISM-900-SET-XD-REP	Qty 3 – 2901540 Qty 2 – 2901533 Qty 1 - 2702122	RAD-IFS-900 RAD-DAIO6-IFS RAD-900-CONF-RF1
2902756	RAD-ISM-900-SET-XD-BUS-2	Qty 3 – 2901540 Qty 4 – 2901533 Qty 1 - 2702122	RAD-IFS-900 RAD-DAIO6-IFS RAD-900-CONF-RF1
2867539	RAD-ISM-900-HOP-US	N/A	N/A - Contact Tech. Service with config#
2900184	RAD-ISM-900-XD-HOPKEY	N/A	N/A - Contact Tech. Service with config#
5605715	RAD-ISM-900-XD-SET 1-8	N/A	N/A
2885605	RAD-ISM-900-XD-BUS	2901540	RAD-IFS-900
2867555	RAD-ISM-900-RS232-BD	2901540*	RAD-IFS-900
2867131	RAD-ISM-900-DATA-BD	2901540*	RAD-IFS-900
2867296	RAD-ISM-900-DATA-BD-BUS	2901540*	RAD-IFS-900
2902277	RAD-ISM-900-DATA-BD-PLUS	2901540*	RAD-IFS-900

Programming cable 2903447 required for advanced configuration.

## PRODUCT DISCONTINUATION

*Should you have any issues with the timeline or content of this discontinuation, please contact Phoenix Contact using the contact information below. Customers should acknowledge receipt of the PD within 30 days of delivery of the PD; provided, however that the failure to acknowledge receipt does not affect the product discontinuation or the effective date thereof.*

**Contact Info:**

JUSTIN SHADE  
(717)944-1300x3524  
[ishade@phoenixcon.com](mailto:ishade@phoenixcon.com)

ZECHARIAH HOFFMAN  
(717)944-1300x3238  
[zhoffman@phoenixcon.com](mailto:zhoffman@phoenixcon.com)

Thank you,



---

Ira Sharp , Product Marketing Manager