



Product Obsolescence Notification

[GCM #10487339]

To: All active customers
From: Molex Micro Products Division
cc:
Date: **December 29, 2010**

Series / Product Family: 5597 series
Part Numbers Affected: See Attached sheet
Product Description: 1.25 FFC CONN ZIF
Product Image: -
Replacements: See Attached sheet
Reason(s) for Obsolescence: Discontinuation of Lead Component
Last Order Entry Date: April 30, 2011
Obsolescence Effective Date: June 30, 2011

PCN Obsolescence special note:

If no last time buy orders are received by April 30, 2011.
Molex reserves the right to terminate production at any time at its own discretion. MOQ and lead time will be negotiated at time of order placement and will be dependent upon material availability. Molex will make all efforts to meet customer order requirements. Orders placed after Obsolescence Notification and subsequently cancelled will be subject to a cancellation charge.

2222 Wellington Court
Lisle, IL 60532
TEL: 630-969-4747 FAX: 630-

www.molex.com

Part Numbers Affected		Replacement	
39513043	5597-04APB	39532044	5597-04APB7F
39513044	5597-04CPB	39532045	5597-04CPB7F
39513063	5597-06APB	39532064	5597-06APB7F
39513093	5597-09APB	39532094	5597-09APB7F
39513103	5597-10APB	39532104	5597-10APB7F
39513113	5597-11APB	39532114	5597-11APB7F
39513154	5597-15CPB	39532155	5597-15CPB7F
39513203	5597-20APB	39532204	5597-20APB7F
39513223	5597-22APB	39532224	5597-22APB7F
39513254	5597-25CPB	39532255	5597-25CPB7F
39513264	5597-26CPB	39532265	5597-26CPB7F
39513274	5597-27CPB	39532275	5597-27CPB7F
39513283	5597-28APB	39532284	5597-28APB7F
39513304	5597-30CPB	39532305	5597-30CPB7F
39513324	5597-32CPB	39532325	5597-32CPB7F