

June 23, 2014

To: Our Valued Customers

Attention: Procurement Manager

Subject: **PLC14032 – Product Discontinuance / Obsolescence Notification**

You are hereby provided notice that the Intersil products included on the attached parts list are being discontinued. As a valued customer, and one that has previously purchased one or more of such parts, Intersil Corporation is pleased to offer you a final life-of-type procurement for these parts. Recognizing that you will need some time to analyze your requirements, Intersil will accept orders for these products through the LTB (Life of Type Buy) / WITHDRAWN date provided in the attached list. All shipments under such orders shall be scheduled no later than the SHIP / OBSOLETE date provided. Intersil will attempt to honor all such purchase orders and scheduled delivery dates, but reserves the right to not accept new orders or to cancel existing orders if such orders cannot be filled through reasonable commercial effort.

Please review the lists and make adjustments as necessary in your database.

The information contained herein is intended for the recipients use only. Please limit the distribution of this material to those individuals within your immediate organization having a need to act upon the information. In the event that additional distribution outside of your internal organization is necessary, please notify Intersil and the distribution list for discontinued products will be updated as appropriate.

If you are considering a redesign, and require assistance, please contact your local Sales or Rep office, or the Intersil Corporate Line, 1-888-468-3774, for our Central Applications Department.

Regards,



Jeffrey R. Touvell

Intersil Corporation

| <b>Exact Intersil Part #<br/>No other variation is<br/>being impacted.</b> | <b>Notice<br/>PLC14032<br/>Issue Date</b> | <b>LTB /<br/>WITHDRAWN<br/>DATE</b> | <b>SHIP /<br/>OBSOLETE<br/>DATE</b> | <b>Replacement/<br/>Similar/<br/>Re-Design</b> |
|--|---|-------------------------------------|-------------------------------------|--|
| EL4501IUZ-T7A  | 23-Jun-2014                               | 23-Dec-2014                         | 23-Jun-2015                         | EL4511CUZ-T7A                                  |
| EL7900ILCZ   | 23-Jun-2014                               | 23-Dec-2014                         | 23-Jun-2015                         | ISL29006IROZ-T7                                |
| EL7900ILCZ-EVALZ   | 23-Jun-2014                               | 23-Dec-2014                         | 23-Jun-2015                         | ISL29006IROZ-EVALZ                             |
| EL7900ILCZ-T7  | 23-Jun-2014                               | 23-Dec-2014                         | 23-Jun-2015                         | ISL29006IROZ-T7                                |
| EL7900ILCZ-T7A   | 23-Jun-2014                               | 23-Dec-2014                         | 23-Jun-2015                         | ISL29006IROZ-T7                                |
| HS0-4080ARH/SAMPLE   | 23-Jun-2014                               | 23-Jun-2014                         | 23-Jun-2014                         | HS0-4080AEH/SAMPLE                             |
| HS0-4080ARH-Q  | 23-Jun-2014                               | 23-Jun-2014                         | 23-Jun-2014                         | HS0-4080AEH-Q                                  |
| HS9-4080ARH/PROTO  | 23-Jun-2014                               | 23-Jun-2014                         | 23-Jun-2014                         | HS9-4080AEH/PROTO                              |
| HS9-4080ARH-8  | 23-Jun-2014                               | 23-Jun-2014                         | 23-Jun-2014                         | HS9-4080AEH-Q                                  |
| HS9-4080ARH-Q  | 23-Jun-2014                               | 23-Jun-2014                         | 23-Jun-2014                         | HS9-4080AEH-Q                                  |
| ISL76161AVZ  | 23-Jun-2014                               | 23-Jun-2014                         | 23-Jun-2014                         | ISL5861IAZ                                     |
| ISL76161AVZ-T  | 23-Jun-2014                               | 23-Jun-2014                         | 23-Jun-2014                         | ISL5861IAZ                                     |
| ISL76161AVZ-TK   | 23-Jun-2014                               | 23-Jun-2014                         | 23-Jun-2014                         | ISL5861IAZ                                     |
| ISL76161AVZ-TR5295   | 23-Jun-2014                               | 23-Jun-2014                         | 23-Jun-2014                         | ISL5861IAZ                                     |
| ISL78020ANZ  | 23-Jun-2014                               | 23-Jun-2014                         | 23-Jun-2014                         | ISL78022ANZ                                    |
| ISL78020ANZ-T  | 23-Jun-2014                               | 23-Jun-2014                         | 23-Jun-2014                         | ISL78022ANZ-T                                  |
| ISL98003CNZ-110  | 23-Jun-2014                               | 23-Dec-2014                         | 23-Jun-2015                         | ISL98002CRZ-170                                |
| ISL98003CNZ-150  | 23-Jun-2014                               | 23-Dec-2014                         | 23-Jun-2015                         | ISL98002CRZ-170                                |
| ISL98003CNZ-165  | 23-Jun-2014                               | 23-Dec-2014                         | 23-Jun-2015                         | ISL98002CRZ-170                                |
| ISL98003CNZ-165S2733   | 23-Jun-2014                               | 23-Dec-2014                         | 23-Jun-2015                         | ISL98002CRZ-170                                |
| ISL98003CNZ-EVALZ  | 23-Jun-2014                               | 23-Dec-2014                         | 23-Jun-2015                         | ISL98002CRZ-EVALZ                              |
| ISL98003INZ-110  | 23-Jun-2014                               | 23-Dec-2014                         | 23-Jun-2015                         | ISL98002CRZ-170                                |
| X9C103SZT1S2490  | 23-Jun-2014                               | 23-Jun-2014                         | 23-Jun-2014                         | X9C103SZT1                                     |
| X9C503SIZT1C7884   | 23-Jun-2014                               | 23-Jun-2014                         | 23-Jun-2014                         | X9C503SIZT1                                    |
| 5962F9961701V9A  | 23-Jun-2014                               | 23-Jun-2014                         | 23-Jun-2014                         | 5962F9961702V9A                                |
| 5962F9961701QSC  | 23-Jun-2014                               | 23-Jun-2014                         | 23-Jun-2014                         | 5962F9961702VXC                                |
| 5962F9961701VSC  | 23-Jun-2014                               | 23-Jun-2014                         | 23-Jun-2014                         | 5962F9961702VXC                                |