

# Product Change Notification

<i>PCN No.:</i>	PCN_01-2020
<i>PCN date:</i>	20.01.2020
<i>Products affected:</i>	All versions: IPS-146, IPS-154, IVS-157, IPM-165, IVS-166, IPS-265, IPS-280, IPS-354, IPS-355, IVS-465, IPS-937, IMS-944, IVQ-959, IVS-979, IPQ05, iSYS-5010, iSYS-5011, iSYS-5020, iSYS-5021
<i>Description of change:</i>	Minor changes in label content. ("FCC ID:"-, "IC:"- and "CE"-notation)
<i>Reason for change:</i>	Legal requirements regarding FCC-, IC- and CE-print
<i>Schedule of change:</i>	Immediately
<i>Anticipated impact:</i>	No impact expected. No changes to the label size or function (datamatrix code).
<i>Contact:</i>	<i>If you have any questions or need additional information, please feel free to contact:</i>  InnoSenT GmbH Frank Schlier Am Roedertor 30 97499 Donnersdorf Germany Tel.: +49 9528 9518-77 E-Mail: frank.schlier@innosent.de
<i>Enclosures:</i>	- - -

*This PCN is only for information. Described changes have no effect on fit/form/function of the product.*

27.01.2020  
**InnoSenT GmbH**