



Expertise Applied | Answers Delivered

Littelfuse, Inc.
8755 West Higgins Road, Suite 500
Chicago, IL 60631 USA
(773) 628-1000

March 8th, 2019

RE: Littelfuse 7762 Obsolescence Notification

Dear Valued Customer,

Littelfuse Inc., as the leading provider of total circuit protection solutions, with a global commitment to providing the highest quality products, regrets to notify you that, due to an unforeseen circumstance with a key supply chain partner, part number 7762 is being made obsolete. This is a very mature product that has seen sharply declining volumes in recent years, and as such, one of our suppliers will no longer make the components necessary for Littelfuse to continue production. The retail-packaged versions, 7762-BX and 7762-WBXV, will be obsoleted in tandem.

We apologize for a lack of advance notification, but due to the nature of the interruption, this obsolescence is effective immediately. We are working to fulfill existing orders on these finished goods, while supplies last. Unfortunately, Littelfuse is unable to offer alternative products as effective replacements for these parts. Please contact your local Littelfuse representative with any additional questions.

Thank you for your continued support,

A handwritten signature in black ink that reads 'Zacke Naughton'.

Zacke Naughton
Global Product Manager
Littelfuse Commercial Vehicle Products