

1 Products affected

Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PUG	Type				
02	007	003	0000002363	See list below	Appliance inlet	1681	

*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

List of part numbers affected				
6173.0009	6173.0018	6173.0026	6173.0034	6173.0042
6173.0010	6173.0019	6173.0027	6173.0035	6173.0043
6173.0011	6173.0020	6173.0028	6173.0036	6173.0044
6173.0012	6173.0021	6173.0029	6173.0037	6173.0045
6173.0013	6173.0022	6173.0030	6173.0038	6173.0046
6173.0014	6173.0023	6173.0031	6173.0039	6173.0047
6173.0015	6173.0024	6173.0032	6173.0040	6173.0048
6173.0016	6173.0025	6173.0033	6173.0041	6173.0049
6173.0017				

2 Type of change

- Change of marking
- Modified label packaging

3 Detailed description of change

Old label	New label
Old product approval	New product approval
<p>Snap-in mounting</p>	<p>Snap-in mounting</p>
<p>Screw-on mounting</p>	<p>Screw-on mounting</p>

Product Change Notification					PCN 1681		D10-011-728
owner	creation date	release date	released by	change order no	rev	page	
sariogar	2016-12-19	2017-05-11	sariogar	2009118	A	1 of 2	

4 Reason of change

- New CCC approval marks.

5 Release date

The change will be rolled-out starting ww 20/2017 (Date code 1720 or higher on label) and lasts approx. 6 months depending on the variant.

6 Impact of change and recommended action

Form	Yes	New approval mark
Fit	No	No change for dimension
Function	No	No change in function
Manufacturing	No	No change for manufacturing site
Label	Yes	New approval marks
Packaging	No	No change in packaging

7 Reference Documents / Attachments

Kind of document	Remarks
Data Sheet 1681	

Product Change Notification					PCN 1681		
owner	creation date	release date	released by	change order no	rev	page	D10-011-728
sariogar	2016-12-19	2017-05-11	sariogar	2009118	A	2 of 2	