

PRODUCT CHANGE NOTIFICATION

Product Category SAFETY PTD 20210216-1

Product Group ID AND SAFETY

ISSUE DATE: 20210216

IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Required)

The Data Access Port greenlee punch line will be discontinued due to no sales in 2 years.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date			
Old product discontinuation date*	2021	5	17

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit’s Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

Impacted Part Numbers	Compatibility Type
DAP3PUNCH-MS	No Replacement
DAP3PUNCH-SS	No Replacement
DAP4PUNCH-MS	No Replacement
DAP4PUNCH-SS	No Replacement