

1 Products affected

Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PUG	Type				
02	007	021	0000002433	See list below	Connector	2572 Appliance Inlet C8	n/a

*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

List of part numbers affected				
3-108-343	3-101-150	3-100-666	6160.0095	6160.0060
6160.0054	6160.0053	6160.0049	6160.0048	6160.0042
6160.0030	6160.0026	6160.0011	6160.0010	6160.0009
6160.0008				





2 Type of change

UL upgrade from UL 498 to UL 60320-1.


Marking for UL rating 7A/125V~ updated. Marking for IEC rating 2.5A/250V~ updated.

In the Chinese test mark CCC, the small S on the right of the third C has been removed.

3 Detailed description of change

Old product rating	New product rating
<p>Terminals in orientation A Front side</p>  <p>Back side</p> 	<p>Terminals in orientation A Front side</p> <p>„S „ removed</p>  <p>Back side</p> 

Product Change Notification					2572 Change of marking		
owner	creation date	release date	released by	change order no	rev	page	D10-055-460
zeierjo	31.03.2021	31.03.2021	muehlema	2020484	B	1 of 2	



4 Reason of change

Standards update according to the new UL/CSA 60320-1.

5 Release date

The change takes effect in ww 19/2021 (Date code 2119 or higher on label).

6 Impact of change and recommended action

Form	Yes	Change of approval and rating marking.
Fit	No	-
Function	No	-
Manufacturing	No	-
Label	No	-
Packaging	No	-

7 Reference Documents / Attachments

Kind of document	Remarks
Data sheet 2572	

Product Change Notification					2572 Change of marking		
owner	creation date	release date	released by	change order no	rev	page	D10-055-460
zeierjo	31.03.2021	31.03.2021	muehlema	2020484	B	2 of 2	