



Product Change Notification

TE Connectivity

Product Change Notification: P-15-011118


PCN Date: 23-JAN-15

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
packaging tape change (PCN, T9A, T9C, T9E, T9S relay series)

Description of Changes
change packaging tape from the tearable tape to transparent tape. This change does not influence the usage.

Packaging Comparison Image

	PCN	T9A/T9C/T9E/T9S	
BEFORE			
AFTER			

Reason for Changes:	
Product improvement.packing tape for automation	
Estimated Dates:	
Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	23-FEB-2015
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	21-MAR-2015

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393210-2	NO			"T9AS1D12-110"			
1-1393210-4	NO			"T9A-S1D12-15", "T9AS1D12-15"			
1-1393210-5	NO			"T9AS1D12-18"			
1-1393210-6	NO			"T9A-S1D12-22", "T9AS1D12-22"			
1-1393210-8	NO			"AMP-1-1393210-8", "F07854-000", "T9AS1D12-24"			
1-1419104-1	NO			"T9AP1D22-18-01"			
1-1419104-6	NO			"T9AS1D22-110"			

1-1419104-7	NO			"T9A-S1D22-12", "T9AS1D22-12"			
1-1649341-4	NO			"T9CP5A52-120"			
1-2027234-0	NO			"T9ES1D12-12"			
1-2027234-3	NO			"T9ES1D22-12"			
1-2027234-8	NO			"T9ES1L14-18"			
1419137-2	NO			"T9AV5D22-24"			
1423029-1	NO			"T9AV5D22-22"			
1423794-1	NO			"T9AS2L22-24"			
1649341-2	NO			"T9CP1A54-240"			
1649341-5	NO			"T9CP1A52-120"			
1649341-8	NO			"T9CP1A54-24"			
2-1393210-0	NO			"T9AS1D12-5"			
2-1393210-2	NO			"T9AS1D12-9"			
2-1393210-5	NO			"T9AS1L12-24"			
2-1393212-6	NO			"T9A-S5L22-12", "T9AS5L22-12"			
2-1419104-1	NO			"T9AS1D22-24"			
2-1419104-2	NO			"T9AS1D22-48"			
2-1649341-0	NO			"T9CP5A54-240"			
2027234-6	NO			"T9ES5D14-12"			
2027234-7	NO			"T9ES1D14-24"			
2027234-9	NO			"T9ES5D24-12"			
2027395-1	NO			"T9SV1K15-12"			
2071229-1	NO			"T9AP2XD56-12"			
2071229-2	NO			"T9AV2XD16-12"			
3-1393210-3	NO			"T9AS5D12-12"			
3-1393210-5	NO			"T9AS5D12-22"			
3-1393210-7	NO			"T9A-S5D12-24", "T9AS5D12-24"			
3-1393210-8	NO			"T9A-S5D12-48", "T9AS5D12-48"			
3-1393210-9	NO			"T9A-S5D12-5", "T9AS5D12-5"			
3-1419104-3	NO			"T9A-S5D22-12", "T9AS5D22-12"			
3-1419104-6	NO			"T9A-S5D22-24", "T9AS5D22-24"			
3-1419104-9	NO			"T9AS5D22-5"			
4-1393210-0	NO			"T9AS5D12-9"			
4-1393210-1	NO			"T9AS5L12-12"			
4-1393210-2	NO			"T9A-S5L12-24", "T9AS5L12-24"			

1-1393210-4	NO			"T9A-S1D12-15", "T9AS1D12-15"			
1-1419104-6	NO			"T9AS1D22-110"			
1-2027234-0	NO			"T9ES1D12-12"			
1-2027234-3	NO			"T9ES1D22-12"			
1-2027234-8	NO			"T9ES1L14-18"			
1423794-1	NO			"T9AS2L22-24"			
2-1393210-2	NO			"T9AS1D12-9"			
2-1649341-0	NO			"T9CP5A54-240"			
2027234-9	NO			"T9ES5D24-12"			
2027395-1	NO			"T9SV1K15-12"			
2071229-1	NO			"T9AP2XD56-12"			
2071229-2	NO			"T9AV2XD16-12"			
3-1393210-5	NO			"T9AS5D12-22"			
4-1393210-0	NO			"T9AS5D12-9"			
4-1393210-2	NO			"T9A-S5L12-24", "T9AS5L12-24"			
4-1419104-2	NO			"T9A-V1L22-24", "T9AV1L22-24"			
7-1461491-6	NO			"PCN- 124D3MHZ,001B"			