

PRODUCT CHANGE NOTIFICATION

PCN#: FIBER CABLE, CONNECTORS 20190529-1

ISSUE DATE: 20190612

IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Not Required for discontinuation)

These legacy, older-style connectors are being discontinued as an extension of the discontinuation started back in 2017. These connectors do not enable current field-termination technology and have been superceded by more current designs. The newer versions were launched two years ago and already have history in the market.

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2017	5	1
Old product discontinuation date*	2019	6	5

***Important:** After old product discontinuation date, the affected part numbers listed above will continue to be available for sale as long as supplies last. Product may be returned up to 60 days after the product continuation date.

IMPACTED PART NUMBER(s)	REPLACEMENT PART NUMBER(s)
FSCMPC6EI	FSC2MC6EI
FSCMPC6EI-C	FSC2MC6EI-C
FSCSCBU-KT	None
FSTMC5BL-C	FST2MC5BL; No 100-pack available
FSTMC6EI-C	FST2MC6EI; No 100-pack available
FSTMC6NBEI	None
FSTMCAQ-C	FST2MCAQ; No 100-pack available
FSTMPC5BL	FST2MC5BL
FSTMPC5BL-C	FST2MC5BL; No 100-pack available
FSTMPC6EI	FST2MC6EI
FSTMPC6EI-C	FST2MC6EI; No 100-pack available
FSTSCBU-C	FST2SCBU; No 100-pack available
FSTSCBUG	FST2SCBU
FSTSCNBBU	None