

CUSTOMER OPERATIONS 160 RIO ROBLES SAN JOSE, CA 95134 PDN #: M001002

DATE: 19-Sep-2020

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommeded Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	DG301AC/D	N/A	21-Mar-2021	17-Sep-2021	Part can no longer be manufactured
Discontinuance	DG303AC/D	N/A	21-Mar-2021	17-Sep-2021	Part can no longer be manufactured
Discontinuance	DS1225Y-200IND+	DS1225AD-200IND+	19-Sep-2020	18-Mar-2021	Part can no longer be manufactured
Discontinuance	MAX1718EEI+	N/A	19-Sep-2021	18-Mar-2022	Part can no longer be manufactured
Discontinuance	MAX20800TPBA+	N/A	19-Sep-2021	18-Mar-2022	Part can no longer be manufactured
Discontinuance	MAX333C/D	N/A	21-Mar-2021	17-Sep-2021	Part can no longer be manufactured
Discontinuance	MAX5975BETE+	N/A	19-Sep-2021	18-Mar-2022	Part can no longer be manufactured
Discontinuance	MAX767EAP+	N/A	19-Sep-2021	18-Mar-2022	Part can no longer be manufactured
Discontinuance	STM1E-SFP02	N/A	20-Dec-2020	18-Jun-2021	Part can no longer be manufactured
Discontinuance	STM1E-SFP08	N/A	20-Dec-2020	18-Jun-2021	Part can no longer be manufactured
Discontinuance	STM1E-SFP35	N/A	20-Dec-2020	18-Jun-2021	Part can no longer be manufactured