



Product Change Notification

TE Connectivity

Product Change Notification: P-22-022807

PCN Date: 30-MAY-22

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
TXR Series / Manufacturing Location Change.

Description of Changes
Adding a new manufacturing location to our internal supply chain, TE ADM Hermosillo, Mx facility has been qualified to machine and plate TXR series in addition to our current manufacturing facility in Hastings, UK. There will be no change in the Form, Fit, or Function of the material.

Reason for Changes:
Dear Customer, as a result of our continuous strive for improving our processes, we hereby inform you about this additional manufacturing location for these products. The transfer is executed by following a strict transfer procedure, which guarantees no negative influence on quality, ability to supply, and form-fit-function of the concerned products. The new manufacturing location is under a certified quality management system according to the standard industry requirements. An internal release based on our specifications will be executed before any parts will be delivered, which guarantees the performance.

Estimated Dates:	
Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	30-AUG-2022
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	30-AUG-2023

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
001445-000	NO			"6-1190010-5", "TXR40AB00-2016A"			
031121-000	NO			"5-1190241-9", "TXR40AB00-2210A"			
031839-000	NO			"9-1190246-1", "TXR40AB00-1004B"			
038625-000	NO			"7-1190296-4", "TXR40AB00-1208B"			
146995-000	NO			"3-1191062-0", "TXR40AB00-1410A"			
150211-000	NO			"2-1191086-1", "TXR54AB00-1206A"			
169309-000	NO			"5-1191232-9", "TXR40AB00-2416A"			
489063-000	NO			"2-1193659-7", "TXR40AC00-1007A"			
497361-000	NO			"7-1193718-5", "TXR40AB00-1208A"			
554173-000	NO			"5-1194375-5", "TXR40AB00-1406A"			
629267-000	NO			"2-1194981-0", "TXR40AB00-1608A"			
919073-000	NO			"3-1197132-7", "TXR40AC00-1004A"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
001445-000	NO			"6-1190010-5", "TXR40AB00-2016A1"			
031121-000	NO			"5-1190241-9", "TXR40AB00-2210A1"			
031839-000	NO			"9-1190246-1", "TXR40AB00-1004B1"			
038625-000	NO			"7-1190296-4", "TXR40AB00-1208B1"			
146995-000	NO			"3-1191062-0", "TXR40AB00-1410A1"			
150211-000	NO			"2-1191086-1", "TXR54AB00-1206A1"			
169309-000	NO			"5-1191232-9", "TXR40AB00-2416A1"			
489063-000	NO			"2-1193659-7", "TXR40AC00-1007A1"			
497361-000	NO			"7-1193718-5", "TXR40AB00-1208A1"			
554173-000	NO			"5-1194375-5", "TXR40AB00-1406A1"			
629267-000	NO			"2-1194981-0", "TXR40AB00-1608A1"			
919073-000	NO			"3-1197132-7", "TXR40AC00-1004A1"			