


<b>PCN Number:</b>	20180309000	<b>PCN Date:</b>	March 12, 2018
<b>Title:</b>	Datasheet for LM3535		
<b>Customer Contact:</b>	<a href="#">PCN Manager</a>	<b>Dept:</b>	Quality Services
<b>Proposed 1<sup>st</sup> Ship Date:</b>	June 12, 2018		
<b>Change Type:</b>			
<input type="checkbox"/>	Assembly Site	<input type="checkbox"/>	Design
<input type="checkbox"/>	Assembly Process	<input checked="" type="checkbox"/>	Data Sheet
<input type="checkbox"/>	Assembly Materials	<input type="checkbox"/>	Part number change
<input type="checkbox"/>	Mechanical Specification	<input type="checkbox"/>	Test Site
<input type="checkbox"/>	Packing/Shipping/Labeling	<input type="checkbox"/>	Test Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Material
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Materials
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Process
<b>Notification Details</b>			
<b>Description of Change:</b>			
Texas Instruments Incorporated is announcing an information only notification. The product datasheet(s) is being updated as summarized below.			
		<b>LM3535</b>	
		<small>SNVS598B – AUGUST 2010 – REVISED MARCH 2018</small>	
<b>Changes from Revision A (May 2013) to Revision B</b>			<b>Page</b>
<ul style="list-style-type: none"> <li>• Added Pin Configuration and Functions section, ESD Ratings table, Feature Description, Device Functional Modes, Application and Implementation, Power Supply Recommendations, Layout, Device and Documentation Support, and Mechanical, Packaging, and Orderable Information ..... 1</li> <li>• Deleted references to "ALS2" option ..... 1</li> <li>• Changed ALS resistor accuracy values from –5% and 5% to –9% and 9% ..... 6</li> </ul>			
The datasheet number will be changing.			
Device Family	Change From:	Change To:	
LM3535	SNVS598A	SNVS598B	
<a href="http://www.ti.com/product/LM3535">http://www.ti.com/product/LM3535</a>			
<b>Reason for Change:</b>			
To accurately reflect device characteristics.			
<b>Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):</b>			
Electrical specification performance changes as indicated above.			
<b>Changes to product identification resulting from this PCN:</b>			
None.			
<b>Product Affected:</b>			
LM3535TME/NOPB	LM3535TMX/NOPB		

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	<a href="mailto:PCNAmericasContact@list.ti.com">PCNAmericasContact@list.ti.com</a>
Europe	<a href="mailto:PCNEuropeContact@list.ti.com">PCNEuropeContact@list.ti.com</a>
Asia Pacific	<a href="mailto:PCNAsiaContact@list.ti.com">PCNAsiaContact@list.ti.com</a>
Japan	<a href="mailto:PCNJapanContact@list.ti.com">PCNJapanContact@list.ti.com</a>