

## Global Change Notification (GCN)

Product Family	HV	10743774
		GCN Number
Series	180081	January 08, 2016
		Date Issued
Reason For Change	Obsolescence	
Change Description	The purpose of this letter is to inform you that due to the LED supplier has stopped making the key component and there is no other source, Molex will obsolete the series number 180081. There will not be any replacement parts.	
Part Numbers Affected	Please refer to CustomerPartList.csv attached to e-mail message.	
Reason For Short Notice Exception	Force Majeure	
Assessment Of Change (How Product Will Be Qualified & Validated)	Series Number 180081 will be obsolete in our SAP system with out replacement.	
Internal Molex Qualification Date (Planned Date Information Available)		
Sample Availability Date (Changed Part)		
Date of Implementation	January 30, 2016	
Method of Identifying Change	N/A	
Recommended Replacement Parts	N/A	
Last Time Buy Date for Obsolete Parts	December 28, 2015	
Last Time Ship Date for Obsolete Parts	January 30, 2016	

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	Agnes Mburu	Agnes.Mburu@molex.com	+31-40-295-8271
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

**Molex, Inc.**  
 2222 Wellington Court  
 Lisle, IL 60532  
 TEL: 630-969-4747  
[www.molex.com](http://www.molex.com)