

**Issue Date:** December 18, 2019

Dear Valued Customer,

This notice is to inform you of a product change affecting selected items that you have purchased from Littelfuse.

***Description of the Change:***

Part Number: 880015 is Obsolete

***Reason for The Change:***

- A key supply chain partner can no longer support the production of a critical component necessary to produce 880015.

***Effective Date of the Change:***

12/18/19

**What You Need to Do:**

Contact your Littelfuse Sales Representative or Customer Service to place a last time buy. Last time buys are only for available on hand quantities.  
Please mark product OB in system and remove from future non last time buy PO's.

If you have any questions, please feel free to contact your Littelfuse Customer Service Representative or your Inside Sales Representative. We appreciate your business and our continued partnership.

Sincerely,

*Joe Plazyk*

Global Product Manager  
Commercial Vehicle Products  
Littelfuse, Inc.