


# Product Change Notice: 3M™ High Routability Internal miniSAS HD Cable Assemblies – Latch Change

Issue Number: 915

Date: April 6, 2015

Effective immediately, latches for all 3M High Routability Internal miniSAS HD Cable assemblies will be shipped in a modified condition, extending the length of the latch by 1.25 mm. This is not a dimension placed on the customer drawings, but under close observation, the change would be apparent. On the previous latch, there were 5 ribs. On the new latch, there are 7 ribs.

This change is designed to enhance the accessibility of the latch. Functionality is not changed. Part numbers and customer drawings are not impacted. Below is an image showing the differences.



**Contact Information:** Charlie Staley, Product Marketing Manager, 512-689-8024, [cstaley@mmm.com](mailto:cstaley@mmm.com)

3M is a trademark of 3M Company.

## Important Notice

All statements, technical information, and recommendations related to 3M's products are based on information believed to be reliable, but the accuracy or completeness is not guaranteed. Before using this product, you must evaluate it and determine if it is suitable for your intended application. You assume all risks and liability associated with such use. Any statements related to the product which are not contained in 3M's current publications, or any contrary statements contained on your purchase order shall have no force or effect unless expressly agreed upon, in writing, by an authorized officer of 3M.

## Warranty; Limited Remedy; Limited Liability.

This product will be free from defects in material and manufacture for a period of one year from the time of purchase. 3M MAKES NO OTHER WARRANTIES INCLUDING, BUT NOT LIMITED TO, ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. If this product is defective within the warranty period stated above, your exclusive remedy shall be, at 3M's option, to replace or repair the 3M product or refund the purchase price of the 3M product. Except where prohibited by law, 3M will not be liable for any direct, indirect, special, incidental or consequential loss or damage arising from this 3M product, regardless of the legal theory asserted.



Electronics Materials Solutions Division, Interconnect Products  
6801 River Place Blvd.  
Austin, TX 78726-9000

1-800-225-5373 [www.3Mconnectors.com](http://www.3Mconnectors.com)

© 3M 2015. All Rights Reserved.