



Expertise Applied | Answers Delivered

Littelfuse, Inc.  
8755 West Higgins Road, Suite 500  
Chicago, IL 60631 USA  
(773) 628-1000

---

April 9<sup>th</sup>, 2019

RE: Littelfuse 81268 Obsolescence Notification

Dear Valued Customer,

Littelfuse Inc., as the leading provider of total circuit protection solutions, with a global commitment to providing the highest quality products, regrets to notify you that part number 81268 is being made obsolete. This is a very mature product that has seen sharply declining volumes in recent years, and as such, we will no longer be able to support the sales of this product.

We apologize for a lack of advance notification, but due to the nature of the interruption, this obsolescence is effective immediately. As a result, we are not able to support a last-time-buy and will be fulfilling existing orders on this part while supplies last. Unfortunately, Littelfuse is unable to offer alternative products as effective replacements for this part. As a suggested alternative supplier for this part, please reach out to the below organization and contact:

KIT GROUP INC.

[officemanager@kitgroupinc.com](mailto:officemanager@kitgroupinc.com)

Please contact your local Littelfuse representative with any additional questions.

Thank you for your continued support,

A handwritten signature in black ink that reads "Zacke Naughton". The signature is written in a cursive, flowing style.

Zacke Naughton  
Global Product Manager  
Littelfuse Commercial Vehicle Products

**LFPCNC0224 Affected Parts List**

**Materials**

81268