



July 31, 2020

Product Advisory #1813 VL-EPU-3312

This is a formal notification that a product supplied by VersaLogic Corporation is being revised. Our records indicate that your company has purchased this product.

Affected Product

| Product | Description | Old Revision Level | New Revision Level |
|----------------|--------------------------------|---------------------------|---------------------------|
| VL-EPU-3312 | Raven Embedded Processing Unit | 1.06A | 1.07A |

Changes Made to the Product

There were no material changes made to this product. The product revision number was changed due to the shared use of the carrier board with a companion product (VL-EPU-4012) which had a BIOS change. The BIOS image for the VL-EPU-3312 product has not changed. This rev number change, needed for traceability in the companion product, has no impact on VL-EPU-3312 systems.

Customer Impact

None.

Fielded Units

Use as is.

Future Shipments

New revision boards will begin shipping in July, 2020.

Additional Information

For additional information or assistance related to this change, please contact VersaLogic Technical Support at Support@VersaLogic.com or call (503) 747-2261.