



Product Change Notification

TE Connectivity

Product Change Notification: P-19-016915

PCN Date: 07-FEB-19

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
 PLUG ASSEMBLY, 40 POSITION

Description of Changes
 TE Connectivity is informing you about a component relocation that involves the listed assembly part numbers. This location change involves the 40 position TPA component used by TE Connectivity in the assembly of the product you buy. The 40 position TPA tool has been transferred to a qualified outside supplier. Final assembly location remains the same.

Reason for Changes:
 Product improvement. TE has a SUPPLIER IN DISTRESS that is unable to meet production requirements, because of that we hereby inform you about transfer of a tool and/or process. The transfer is executed by following a strict transfer procedure to maintain quality, ability to supply specifications of the concerned products. The new manufacturing location is under a certified quality management system according to the standard automotive requirements. An internal release based on our specifications will be executed before any parts will be delivered. Your timely review is essential and required to mitigate any delays as TE will not bear liability for supply delays due to lack of timely approval.

Estimated Dates:

| | |
|---|---|
| Last Order Date (Obsolete Parts Only): | First Date To Ship (Changed Parts Only): |
| | 22-FEB-2019 |
| Last Ship Date (Obsolete Parts Only): | Last Date for Mixed Shipments: (Changed Parts Only): |
| | No Mixed Shipments |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|---------------------------|---------------------------|------------------|----------------------|----------------------|------------------------|---------------------------------|---------------------------|
| 1488846-4 | NO | | | | | | |
| 1488846-6 | NO | | | | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|---------------------------|---------------------------|------------------|----------------------|----------------------|------------------------|---------------------------------|---------------------------|
| 1488846-4 | NO | | | | | | |
| 1488846-6 | NO | | | | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|---------------------------|---------------------------|------------------|----------------------|----------------------|------------------------|---------------------------------|---------------------------|
| 1488846-4 | NO | | | | | | |
| 1488846-6 | NO | | | | | | |