

Product Discontinuation

PDN-ICC-8165-2022

Business Unit	Product Line Code	Type of Change	Action	Date of Issue
ICC - Industrial Cabinet	BE1	Product Discontinuation	Notify Distributors and Field	8/5/2022

Phoenix Contact's factory has announced the following product(s) is going to be discontinued. Existing specifications will be met or exceeded. Technical support of the discontinued product will continue, as required. Please review and acknowledge this document and take the appropriate action with respect to your existing inventory and ordering replacement parts.

Description for Product Discontinuation
Discontinuation due to availability of alternative products. Increased availability through portfolio streamlining.

Stock Status
Can existing stock still be used? Yes
Is mixture of stock acceptable? Yes

Transaction Dates
Last Buy from Phoenix Contact: 10/31/2022
Last Scheduled Ship from Phoenix Contact: 10/31/2022

Should you have any issues with the timeline or content of this product discontinuation, please contact Phoenix Contact using the information below. Customers should acknowledge receipt of the PDN within 30 days of delivery of the PDN; provided, however, that the failure to acknowledge receipt does not affect the product discontinuation or the effective date thereof.

Contact Info:

Eric Silvestri
esilvestri@phoenixcontact.com

Thank you,

Cory Myer

Associate Product Marketing Manager ICC



Phoenix Contact Inc.
P.O. BOX 4100
Harrisburg, PA 17111-0100
Phone: 717-944-1300

Product Discontinuation

Discontinued Part #	Type Description	Replacement Part #	Type Description
3059249	RSC 5-F/12	3059252	RBO 5-F/12
3059171	RSC 4-F/4	3058237	RBO 5-F/4
3059236	RSC 5-F/8	3058253	RBO 5-F/8
3059197	RSC 4-F/8	3058253	RBO 5-F/8
3059184	RSC 4-F/6	3058240	RBO 5-F/6
3075919	RSC 6-F	3075935	RBO 6-F
3059223	RSC 5-F/6	3058240	RBO 5-F/6
3059207	RSC 4-F/12	3059252	RBO 5-F/12
3059210	RSC 5-F/4	3058237	RBO 5-F/4
3058156	RSC 5-F	3058237	RBO 5-F/4
3058130	RSC 4-F	3058237	RBO 5-F/4