

Product Change Notification

PCN-AS-8051-2022

Business Unit	Product Line Code	Type of Change	Action	Date of Issue
AS - Automation Systems	DRI	Product Change Notification	Notify Distributors and Field	7/25/2022

The following Phoenix Contact products have been modified. Existing specifications will be met or exceeded. Please review and acknowledge this document and inform your personnel as needed.

Description for Product Change Notification
DHCP behavior improved // DCP behavior in VLAN improved // Improved stability // Improved integration of IOL-CONF // WBM extended // Security: Port disconnection // Security: Password for FTP diagnostics // The firmware is available in the Download Center. For detailed information, please refer to the change notes for the firmware.


Stock Status
Can existing stock still be used?
Is mixture of stock acceptable?

Transaction Dates	
Date modification goes into effect from Germany:	4/1/2022
Expected first shipment (from Phoenix Contact) of the modified products(s):	4/1/2022

Should you have any issues with the timeline or content of this product change, please contact Phoenix Contact using the information below. Customers should acknowledge receipt of the PCN within 30 days of delivery of the PCN; provided, however, that the failure to acknowledge receipt does not affect the product change or the effective date thereof.

Contact Info:
Jason Haldeman
jhaldeman@phoenixcontact.com

Thank you,



Zachary Stank
Product Marketing Manager



Phoenix Contact Inc.
P.O. BOX 4100
Harrisburg, PA 17111-0100
Phone: 717-944-1300

Product Change Notification

Part #	Type Description
2688459	AXL F BK ETH
2701949	AXL F BK ETH XC