

## PRODUCT DISCONTINUATION

### #PD-ION-K0YP-15

Business Unit	Product Line Code	Type of Change	Action	Date of issue
ION	CNI		Notify Distributors and Field	6/29/2015

*Phoenix Contact's factory has announced the following product(s) is going to be discontinued. Existing specifications will be met or exceeded. Technical support of the discontinued product will continue, as required. Please review and acknowledge this document and take the appropriate action with respect to your existing inventory and ordering replacement parts.*

#### Reason for Discontinuation:

The following Inline Modular CAN Bus Couplers have reached end of life and will no longer be available for purchase.

This discontinuation is being forced because the necessary components are no longer available, A replacement is currently in development but we don't expect availability until late next year.

#### Warranty Information:

--

#### Stock Status

Can existing stock still be used? Y

Is mixture of stock acceptable? Y

#### Transaction Dates:

Last Buy from Phoenix Contact: 8/31/2015

Last Scheduled Ship from Phoenix Contact: 10/31/2015

## PRODUCT DISCONTINUATION #PD-ION-K0YP-15

*Should you have any issues with the timeline or content of this discontinuation, please contact Phoenix Contact using the contact information below. Customers should acknowledge receipt of the PD within 30 days of delivery of the PD; provided, however that the failure to acknowledge receipt does not affect the product discontinuation or the effective date thereof.*

**Contact Info:**

JASON HALDEMAN  
 Product Marketing Lead Specialist  
 (717)944-1300x3746  
 jhaldeman@phoenixcon.com

Thank you,




---

, Product Marketing Manager

Discontinued Part#	Type Description	Replacement Part#	Type Description
2718701 2702130	IL CAN BK-TC-PAC IL CAN BK-TC-XC-PAC		