



Product Change Notification

TE Connectivity

Product Change Notification: P-20-020044

PCN Date: 17-NOV-20

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Power F Relay

Description of Changes

Dear Customer, within our ongoing efforts to optimize our product portfolio throughout the lifecycle, we hereby inform you upfront about a tool replacement for Power F Frame to continuously meet all specification requirements. This PCN is for information purposes only, with no need to release this change.

Reason for Changes:

Product improvement.Current running manufacturing tool is worn out.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	27-NOV-2020
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393304-1	NO			"V23134J1053D642"			
1-1414147-0	NO			"V23134J0052X429"			
1-1414167-0	NO						
1-1414168-0	NO						
1393302-6	NO			"VF4-15F13"			
1393303-9	NO			"V23134-B0053-C642", "V23134B53C642"			
1393304-9	NO			"V23134J1052D642"			
2-1393302-2	NO			"V23134A 52C643", "V23134A0052C643", "D33228-000", "AMPS-2-1393302-2"			
3-1393303-4	NO			"V23134B1052C642"			
3-1393303-7	NO			"V23134B1053C642"			
3-1415001-2	NO						
5-1393302-1	NO			"V23134A 53C643"			
5-1393302-2	NO			"V23134-A0053-G243", "V23134A53G243"			
5-1393302-8	NO			"V23134A1052C643"			
7-1393302-5	NO			"V23134B 52C642"			
9-1393303-7	NO			"V23134J 53D642"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393304-1	NO			"V23134J1053D642"			
1-1414147-0	NO			"V23134J0052X429"			
1-1414167-0	NO						
1-1414168-0	NO						
1393302-6	NO			"VF4-15F13"			
1393303-9	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
				"V23134-B0053-C642", "V23134B53C642"			
1393304-9	NO			"V23134J1052D642"			
2-1393302-2	NO			"V23134A 52C643", "V23134A0052C643", "D33228-000", "AMPS-2-1393302-2"			
3-1393303-4	NO			"V23134B1052C642"			
3-1393303-7	NO			"V23134B1053C642"			
3-1415001-2	NO						
5-1393302-1	NO			"V23134A 53C643"			
5-1393302-2	NO			"V23134-A0053-G243", "V23134A53G243"			
5-1393302-8	NO			"V23134A1052C643"			
7-1393302-5	NO			"V23134B 52C642"			
9-1393303-7	NO			"V23134J 53D642"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393304-1	NO			"V23134J1053D642"			
1-1414167-0	NO						
1393303-9	NO			"V23134-B0053-C642", "V23134B53C642"			
1393304-9	NO			"V23134J1052D642"			
2-1393302-2	NO			"V23134A 52C643", "V23134A0052C643", "D33228-000", "AMPS-2-1393302-2"			
3-1393303-4	NO			"V23134B1052C642"			
3-1393303-7	NO			"V23134B1053C642"			
3-1415001-2	NO						
5-1393302-1	NO			"V23134A 53C643"			
5-1393302-2	NO			"V23134-A0053-G243", "V23134A53G243"			
7-1393302-5	NO			"V23134B 52C642"			
9-1393303-7	NO			"V23134J 53D642"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
2-1393302-2	NO			"V23134A 52C643", "V23134A0052C643", "D33228-000", "AMPS-2-1393302-2"			
5-1393302-8	NO			"V23134A1052C643"			