



Product Change Notification

TE Connectivity

Product Change Notification: P-17-014015

PCN Date: 03-JAN-17

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Product produced at TE Rock Hill, SC

Description of Changes

TE Connectivity (TE) is moving manufacturing location of the products listed below from TE Rock Hill to TE Guangdong. Please contact your TE Sales Engineer with questions. The specific part numbers are detailed below.

Reason for Changes:

After an extensive analysis of our TE business unit operations, we are announcing a plan to simplify our manufacturing footprint. As a result of this plan, product produced at our TE Rock Hill, SCOR Hermosillo, MX facilities will be relocated to other TE Connectivity locations (North America and China) by the end of November 2017. Additionally, we will relocate some product produced at our TE Dongguan China facility for our North American market to our Hermosillo, MX facility by the end of November 2017.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	26-JUN-2017
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	05-MAR-2018

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-552011-1	NO			"403421977", "801286-000", "HUB-16903"			
1-552027-1	NO			"452852-000", "HUB-21009", "4-24134-0010"			
1-552296-1	NO			"5W1271-000", "4-24036-0190", "6428336800"			
1-552496-1	NO			"CC1538-000", "AMP-1-0552496-1", "1390256", "1205025"			
1-558693-1	NO			"AMP-1-0558693-1", "D07336-000", "1085025"			
2-552008-1	NO			"1233095"			
2-552079-1	NO						
229909-1	NO			"1162696", "1193318", "4-16211-7320"			
229968-1	NO			"900291444", "221322-000", "1162810", "4-16211-7310"			
229969-1	NO			"822968-000", "HUB-40283", "1193320", "4-16211-7311"			
229969-2	NO			"420920-000", "1191403", "4-24036-0030"			
3-552008-1	NO			"1080139", "500-060-2303"			
3-552414-1	NO						
4-552008-1	NO			"4-27046-4675"			
5229996-3	NO			"1353453"			
552008-1	NO		A1548-ND	"E97943-000", "AMP-0-0552008-1", "500-095-1116", "4-16211-7367", "4-27051-2334", "500-020-2061", "6428318801"			
552496-1	NO			"CA7203-000", "AMP-0-0552496-1", "500-020-2514", "4-16211-7335"			
552760-1	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-558693-1	NO			"AMP-1-0558693-1", "D07336-000", "1085025"			
229909-1	NO			"1162696", "1193318", "4-16211-7320"			
229969-2	NO			"420920-000", "1191403", "4-24036-0030"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-552011-1	NO			"403421977", "801286-000", "HUB-16903"			
1-552027-1	NO			"452852-000", "HUB-21009", "4-24134-0010"			
1-552496-1	NO			"CC1538-000", "AMP-1-0552496-1", "1390256", "1205025"			
2-552008-1	NO			"1233995"			
2-552079-1	NO						
229969-1	NO			"822968-000", "HUB-40283", "1193320", "4-16211-7311"			
3-552008-1	NO			"1080139", "500-060-2303"			
3-552414-1	NO						
4-552008-1	NO			"4-27046-4675"			
552008-1	NO		A1548-ND	"E97943-000", "AMP-0-0552008-1", "4-16211- 7367", "4-27051-2334", "500-020-2061", "500- 095-1116", "6428318801"			
552496-1	NO			"CA7203-000", "AMP-0-0552496-1", "500-020- 2514", "4-16211-7335"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-552011-1	NO			"403421977", "801286-000", "HUB-16903"			
1-552027-1	NO			"452852-000", "HUB-21009", "4-24134-0010"			
1-552496-1	NO			"CC1538-000", "AMP-1-0552496-1", "1390256", "1205025"			
1-558693-1	NO			"AMP-1-0558693-1", "D07336-000", "1085025"			
2-552008-1	NO			"1233995"			
2-552079-1	NO						
229909-1	NO			"1162696", "1193318", "4-16211-7320"			
229969-1	NO			"822968-000", "HUB-40283", "1193320", "4-16211-7311"			
229969-2	NO			"420920-000", "1191403", "4-24036-0030"			
3-552008-1	NO			"1080139", "500-060-2303"			
3-552414-1	NO						
4-552008-1	NO			"4-27046-4675"			
552008-1	NO			"E97943-000", "AMP-0-0552008-1", "4-16211- 7367", "4-27051-2334", "500-020-2061", "500- 095-1116", "6428318801"			
552496-1	NO			"CA7203-000", "AMP-0-0552496-1", "500-020- 2514", "4-16211-7335"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-552296-1	NO			"5W1271-000", "4-24036-0190", "6428336800"			
1-552496-1	NO			"CC1538-000", "AMP-1-0552496-1", "1390256", "1205025"			
1-558693-1	NO			"AMP-1-0558693-1", "D07336-000", "1085025"			
229909-1	NO			"1162696", "1193318", "4-16211-7320"			
229968-1	NO			"900291444", "221322-000", "1162810", "4-16211-7310"			
3-552008-1	NO			"1080139", "500-060-2303"			
4-552008-1	NO			"4-27046-4675"			
5229996-3	NO			"1353453"			
552008-1	NO		A1548-ND	"E97943-000", "AMP-0-0552008-1", "4-16211-7367", "4-27051-2334", "500-020-2061", "500-095-1116", "6428318801"			
552760-1	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-552296-1	NO			"5W1271-000", "4-24036-0190", "6428336800"			
1-552496-1	NO			"CC1538-000", "AMP-1-0552496-1", "1390256", "1205025"			
1-558693-1	NO			"AMP-1-0558693-1", "D07336-000", "1085025"			
229968-1	NO			"900291444", "221322-000", "1162810", "4-16211-7310"			
3-552008-1	NO			"1080139", "500-060-2303"			
4-552008-1	NO			"4-27046-4675"			
5229996-3	NO			"1353453"			
552008-1	NO			"E97943-000", "AMP-0-0552008-1", "4-16211-7367", "4-27051-2334", "500-020-2061", "500-095-1116", "6428318801"			
552760-1	NO						