



Product Change Notification

TE Connectivity

Product Change Notification: P-18-016420

PCN Date: 02-OCT-18

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

TE Corcom EMI Filters

Description of Changes

Manufacturing location change. Following Part Numbers will be transferred from TE Connectivity Juarez, Mexico to TE Connectivity Hermosillo, Mexico.

Reason for Changes:

Dear Customer, we hereby inform you about a transfer of tools and/or processes. The transfer follows a strict procedure, which fully maintains quality, ability to supply and form-fit-function of the concerned products. The new manufacturing location operates under a certified quality management system in accordance with standard ISO requirements. A TE-internal release test based on the relevant part specifications will be executed before delivery.

Estimated Dates:

| | |
|---|---|
| Last Order Date (Obsolete Parts Only): | First Date To Ship (Changed Parts Only): |
| | 21-DEC-2018 |
| Last Ship Date (Obsolete Parts Only): | Last Date for Mixed Shipments: (Changed Parts Only): |
| | 27-DEC-2019 |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number (s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|-----------------------------|---------------------------|------------------|----------------------|-----------------------|------------------------|---------------------------------|---------------------------|
| 1-1609112-3 | NO | | | "15CBS1" | | | |
| 1-6609101-2 | NO | | | "PS0SXD000" | | | |
| 1-6609113-3 | NO | | | "10CFE1" | | | |
| 1-6609114-0 | NO | | | "6CHS1" | | | |
| 1-6609122-1 | NO | | | "4EDL1S" | | | |
| 1-6609122-8 | NO | | | "4EDL4M" | | | |
| 1-6609941-4 | NO | | | "PM00SDHXB" | | | |
| 1-6609951-6 | NO | | | "PS0SSDSXA" | | | |
| 1-6609951-7 | NO | | | "PS0SSDSXB" | | | |
| 1609080-1 | NO | | | "AA400" | | | |
| 1609112-1 | NO | | | "10CBE1" | | | |
| 1609112-8 | NO | | 10CS1 | "10CS1" | | | |
| 2-6609104-9 | NO | | | "PE0S0DSXB" | | | |
| 2-6609122-2 | NO | | | "6EDL1SM" | | | |
| 2-6609122-5 | NO | | | "6EDL4CM" | | | |
| 3-6609952-7 | NO | | | "PS000DHXB" | | | |
| 3-6609956-7 | NO | | | "PE000D000" | | | |
| 4-1609154-6 | NO | | | "PE000DMXE" | | | |
| 4-1609154-9 | NO | | | "PE0S0SMXE" | | | |
| 4-1609156-1 | NO | | | "PM0S0SMXE" | | | |
| 4-6609106-5 | NO | | | "PS0S0SHXB" | | | |
| 4-6609929-2 | NO | | | "PE0S0DHXB" | | | |
| 4-6609959-3 | NO | | | "PM0SSSBX0" | | | |
| 5-6609952-5 | NO | | | "PS000SHXB" | | | |
| 6-6609930-8 | NO | | | "PE000DHXB" | | | |
| 6-6609959-6 | NO | | | "PM0S0DBX0" | | | |
| 6609058-1 | NO | | | "3VAQ8F" | | | |
| 6609058-3 | NO | | | "6VAQ8F" | | | |
| 6609069-3 | NO | | | "16FC10" | | | |
| 6609072-3 | NO | | | "45AYP6C" | | | |
| 6609074-1 | NO | | | "15DCF6" | | | |
| 6609074-7 | NO | | | "100DCF6" | | | |
| 6609101-2 | NO | | | "PS000D000" | | | |

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number (s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|-----------------------------|---------------------------|------------------|----------------------|-----------------------|------------------------|---------------------------------|---------------------------|
| 6609109-6 | NO | | | "PE00DLXC" | | | |
| 6609120-1 | NO | | | "3EZLA2S" | | | |
| 6609121-3 | NO | | | "6EL1SCM" | | | |
| 6609121-4 | NO | | | "6EL1SM" | | | |
| 6609121-7 | NO | | | "6EL4CM" | | | |
| 6609122-2 | NO | | | "2EDL1SC" | | | |
| 6609122-3 | NO | | | "2EDL1SCM" | | | |
| 6609122-5 | NO | | | "2EDL4" | | | |
| 6609212-6 | NO | | | "RJ11-6N3-B" | | | |
| 6609963-5 | NO | | | "PS0SSDBX0" | | | |
| 7-6609959-8 | NO | | | "PMOS0S000" | | | |
| 8-6609928-6 | NO | | | "PE0SSSHXB" | | | |
| 8-6609955-8 | NO | | | "PE0S0DBX0" | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number (s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|-----------------------------|---------------------------|------------------|----------------------|-----------------------|------------------------|---------------------------------|---------------------------|
| 1-1609112-3 | NO | | | "15CBS1" | | | |
| 1-6609101-2 | NO | | | "PS0SX000" | | | |
| 1-6609113-3 | NO | | | "10CFE1" | | | |
| 1-6609122-1 | NO | | | "4EDL1S" | | | |
| 1-6609941-4 | NO | | | "PM00SDHXB" | | | |
| 1609112-1 | NO | | | "10CBE1" | | | |
| 1609112-8 | NO | | 10CS1 | "10CS1" | | | |
| 2-6609104-9 | NO | | | "PE0S0DSXB" | | | |
| 2-6609122-2 | NO | | | "6EDL1SM" | | | |
| 2-6609122-5 | NO | | | "6EDL4CM" | | | |
| 3-6609956-7 | NO | | | "PE00D000" | | | |
| 4-1609154-6 | NO | | | "PE00DMXE" | | | |
| 4-1609154-9 | NO | | | "PE0S0SMXE" | | | |
| 4-1609156-1 | NO | | | "PM0S0SMXE" | | | |
| 4-6609929-2 | NO | | | "PE0S0DHXB" | | | |
| 4-6609959-3 | NO | | | "PM0SSSBX0" | | | |
| 6-6609930-8 | NO | | | "PE00DHXB" | | | |
| 6-6609959-6 | NO | | | "PM0S0DBX0" | | | |
| 6609058-1 | NO | | | "3VAQ8F" | | | |
| 6609058-3 | NO | | | "6VAQ8F" | | | |
| 6609069-3 | NO | | | "16FC10" | | | |
| 6609072-3 | NO | | | "45AYP6C" | | | |
| 6609074-1 | NO | | | "15DCF6" | | | |
| 6609074-7 | NO | | | "100DCF6" | | | |
| 6609101-2 | NO | | | "PS00D000" | | | |
| 6609120-1 | NO | | | "3EZLA2S" | | | |
| 6609121-7 | NO | | | "6EL4CM" | | | |
| 6609122-2 | NO | | | "2EDL1SC" | | | |
| 6609122-3 | NO | | | "2EDL1SCM" | | | |
| 6609212-6 | NO | | | "RJ11-6N3-B" | | | |
| 6609963-5 | NO | | | "PS0SSDBX0" | | | |
| 7-6609959-8 | NO | | | "PMOS0S000" | | | |
| 8-6609955-8 | NO | | | "PE0S0DBX0" | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number (s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|-----------------------------|---------------------------|------------------|----------------------|-----------------------|------------------------|---------------------------------|---------------------------|
| 1-1609112-3 | NO | | | "15CBS1" | | | |

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number (s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|-----------------------------|---------------------------|------------------|----------------------|-----------------------|------------------------|---------------------------------|---------------------------|
| 1-6609114-0 | NO | | | "6CHS1" | | | |
| 1609112-1 | NO | | | "10CBE1" | | | |
| 4-1609154-6 | NO | | | "PE000DMXE" | | | |
| 4-1609154-9 | NO | | | "PE0S0SMXE" | | | |
| 4-6609959-3 | NO | | | "PMOSSSBX0" | | | |
| 6-6609959-6 | NO | | | "PMOS0DBX0" | | | |
| 6609109-6 | NO | | | "PE000DLXC" | | | |
| 6609121-3 | NO | | | "6EL1SCM" | | | |
| 6609122-5 | NO | | | "2EDL4" | | | |
| 8-6609928-6 | NO | | | "PE0SSSHXB" | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number (s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|-----------------------------|---------------------------|------------------|----------------------|-----------------------|------------------------|---------------------------------|---------------------------|
| 1-6609114-0 | NO | | | "6CHS1" | | | |
| 1-6609122-8 | NO | | | "4EDL4M" | | | |
| 1-6609951-6 | NO | | | "PS0SSDSXA" | | | |
| 1-6609951-7 | NO | | | "PS0SSDSXB" | | | |
| 1609080-1 | NO | | | "AA400" | | | |
| 3-6609952-7 | NO | | | "PS000DHXB" | | | |
| 3-6609956-7 | NO | | | "PE000D000" | | | |
| 4-1609154-6 | NO | | | "PE000DMXE" | | | |
| 4-6609106-5 | NO | | | "PS0S0SHXB" | | | |
| 5-6609952-5 | NO | | | "PS000SHXB" | | | |
| 6-6609959-6 | NO | | | "PMOS0DBX0" | | | |
| 6609109-6 | NO | | | "PE000DLXC" | | | |
| 6609121-4 | NO | | | "6EL1SM" | | | |
| 6609122-3 | NO | | | "2EDL1SCM" | | | |
| 8-6609928-6 | NO | | | "PE0SSSHXB" | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number (s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|-----------------------------|---------------------------|------------------|----------------------|-----------------------|------------------------|---------------------------------|---------------------------|
| 1-1609112-3 | NO | | | "15CBS1" | | | |
| 1-6609114-0 | NO | | | "6CHS1" | | | |
| 1-6609951-6 | NO | | | "PS0SSDSXA" | | | |
| 1-6609951-7 | NO | | | "PS0SSDSXB" | | | |
| 1609080-1 | NO | | | "AA400" | | | |
| 1609112-1 | NO | | | "10CBE1" | | | |
| 3-6609956-7 | NO | | | "PE000D000" | | | |
| 4-1609154-6 | NO | | | "PE000DMXE" | | | |
| 4-1609154-9 | NO | | | "PE0S0SMXE" | | | |
| 4-6609106-5 | NO | | | "PS0S0SHXB" | | | |
| 4-6609959-3 | NO | | | "PMOSSSBX0" | | | |
| 5-6609952-5 | NO | | | "PS000SHXB" | | | |
| 6-6609959-6 | NO | | | "PMOS0DBX0" | | | |
| 6609109-6 | NO | | | "PE000DLXC" | | | |
| 6609121-3 | NO | | | "6EL1SCM" | | | |
| 6609121-4 | NO | | | "6EL1SM" | | | |
| 6609122-3 | NO | | | "2EDL1SCM" | | | |
| 6609122-5 | NO | | | "2EDL4" | | | |
| 8-6609928-6 | NO | | | "PE0SSSHXB" | | | |