

Product Discontinuation

2008-11-03

!! UPDATE !!

OS-PD-2008-005

Last order:	10. Jan 2009
Last delivery:	01. Dez 2009

Reason: Streamline of product portfolio / Change to thinfilm chip technology

DISCONTINUED				NEW (REPLACEMENT)							
Device	Ordering Code	Function	Package	Device	Ordering Code	Device	Ordering Code	Device	Ordering Code	Function	Package
SFH 4301	Q62702P5166	Emitter	3mm Radial	SFH 4341 ⁴⁾	Q65110A8092	SFH 4350	Q65110A2091	--	--	Emitter	3mm Radial
SFH 4501	Q62702P5061	Emitter	5mm Radial	SFH 4545 ⁴⁾	Q65110A8095	SFH 4550	Q65110A1772	SFH 4555 ¹⁾	Q65110A7344	Emitter	5mm Radial
SFH 4502	Q62702P5062	Emitter	5mm Radial	SFH 4546 ⁴⁾	Q65110A8096	SFH 4556	Q65110A6087	--	--	Emitter	5mm Radial
SFH 4502 RN25A	Q65110A7720	Emitter	5mm Radial	SFH 4546 ⁴⁾	Q65110A8096	SFH 4556	Q65110A6087	--	--	Emitter	5mm Radial
SFH 4503	Q62702P5305	Emitter	5mm Radial	SFH 4545 ⁴⁾	Q65110A8095	SFH 4550	Q65110A1772	SFH 4555 ¹⁾	Q65110A7344	Emitter	5mm Radial
SFH 4503 RN25A	Q65110A2909	Emitter	5mm Radial	SFH 4545 ⁴⁾	Q65110A8095	SFH 4550	Q65110A1772	SFH 4555 ¹⁾	Q65110A7344	Emitter	5mm Radial

1) ~~samples available: January 2009~~

SOP: depending on product, pls contact your sales team

SFH 4341, SFH 4545, SFH 4546 SFH 4555 delayed

Please use the other replacements