

## Not Recommended for New Design: AYF53XX65 FPC Connector

NRFND.Ref. #ACBD.257

04.15.14

About this Notice:	AYF53XX65 FPC Connector is immediately Not Recommended For New Design.
Features:	Please reference Product Change Notice dated 1.17.2014 for details on replacement part AYF53XX65T.
Effective Date:	Immediate.
Affected Parts and/or Replacements:	AYF53XX65 only.
Datasheet(s):	See attachment.
Notes:	