

1 Products affected

Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PGU	Type				
03	009	010	0000003008	1301.9303	Switches	LPH	
03	009	010	0000003008	1301.9305	Switches	LPH	
03	009	010	0000003008	1301.9307	Switches	LPH	


*SBU (2-digit) / PG (3-digit) / PGU (3-digit) / Type (10-digit)

2 Type of change

Actuator dimensions have changed, see table below

3 Detailed description of change

Part no.	Dimension A old [mm]	Dimension A new [mm]
1301.9303	Ø 3.2	Ø 3.3
1301.9305	Ø 3.1	Ø 3.3
1301.9307	Ø 3.0	Ø 3.4



Tolerance +/- 0.1

4 Reason for change

Redesign and improvement of tooling

5 Released date

Release for series production

ww 12/2013

6 Impact of change and recommended action

Form: Yes, see chapter 3
Fit: Yes, see chapter 3
Function: No influence
Production Site: No influence

LPH					0118.2163	
creation date	created by	release date	released by	notification no.	revision	page
2013-03-12	bisanger	2013-03-19	bisanger	24506	-	1 of 1