



Display Division
KYOCERA Industrial Ceramics Corporation
46723 Five Mile Road
Plymouth, MI 48170 USA
Tel: 734-416-8500
Fax: 734-416-8520
www.kyocera-display.com

Product Change Notification

Date: Dec. 16th, 2015

Dear Valued Customer,

Thank you for choosing KYOCERA as your LCD solution provider. We appreciate the opportunity to support your business. This letter is to provide you additional information on a previously announced product change notice.

1. Reason for the ECN:

To restructure our passive product line, we decided to consolidate production into one factory, located in China. For products that will be transferred to China, there will be a part number change.

2. Schedule:

For new part number and schedule, please refer the tables on next page for details.

<Table 1>

- Target sample: by Dec. 2015
- Target to obtain customer's approval: Mar 30th, 2016

<Table 2>

- Target sample: Q1. 2016
- Target to obtain customer's approval: Jun 30th, 2016.

Thank you in advance for your understanding and your cooperation. If you have any questions, please contact your KYOCERA sales representative.

Sincerely yours,

KYOCERA Industrial Ceramics Inc
Display Division

Table 1: Sample available in Dec, 2015, LTB date: Mar 30th, 2016

Part Code	Part Number	New Part Number	Sample	LTB date
351405AN	F-51405GNB-LW-ANN	No change	Dec. End	Mar 30 th , 2016
351505AP	C-51505NFJ-SLW-APN	C-51505NFJ-SLW-AQN	Now	Mar 30 th , 2016
351847AE	C-51847NFJ-SLW-AEN	C-51847NFJ-SLW-AFN	Now	Mar 30 th , 2016
355472AF	F-55472GNFJ-SLW-AFN	F-55472GNFJ-SLW-AHN	Now	Mar 30 th , 2016
355472AG	F-55472GNBJ-LW-AGN	F-55472GNBJ-LW-AIN	Dec. End	Mar 30 th , 2016
355471AI	F-55471GNFJ-SLW-AIN	F-55471GNFJ-SLW-AMN	Now	Mar 30 th , 2016
355471AH	F-55471GNBJ-LW-AHN	F-55471GNBJ-LW-ANN	Now	Mar 30 th , 2016
56015AA	F-56015GNB-LW-AAN	F-56015GNB-LW-AFN	Dec. End	Mar 30 th , 2016
55605AC	C-55605GNFU-LW-ACN	C-55605GNFU-LW-AEN	Now	Mar 30 th , 2016
351553AF	F-51553GNBJ-LW-AFN	F-51553GNBJ-LW-AGN	Now	Mar 30 th , 2016
351762AC	F-51211FNWJU-T-ACN	F-51211FNWJU-T-AEN	TBD	Mar 30 th , 2016
55993AD	F-55993GNFJ-SLM-ADN	F-55993GNFJ-SLM-AEN	TBD	Mar 30 th , 2016
351477AL	F-51477GNF-SLY-ALN	No change	TBD	Mar 30 th , 2016

Table 2: PN and sample will be updated in Q1, 2016, with LTB date Jun 30th, 2016

Part Code	Part Number	New Part Number	Sample	LTB date
351505AJ	C-51505NFQJ-LB-AJN	TBA	TBD	Jun 30 th , 2016
351505AK	C-51505NFQJ-LG-AKN	TBA	TBD	Jun 30 th , 2016
351505AL	C-51505NFQJ-LW-ALN	TBA	TBD	Jun 30 th , 2016
351847AA	C-51847NFQJ-LW-AAN	TBA	TBD	Jun 30 th , 2016
355472AB	F-55472GNFQJ-LW-ABN	TBA	TBD	Jun 30 th , 2016
355472AD	F-55472GNFQJ-LG-ADN	TBA	TBD	Jun 30 th , 2016
355472AE	F-55472GNFQJ-LB-AEN	TBA	TBD	Jun 30 th , 2016
355471AC	F-55471GNFQJ-LW-ACN	TBA	TBD	Jun 30 th , 2016
351394AF	F-51394FNFJ-SEW-AFN	No change	TBD	Jun 30 th , 2016
351762AC	F-51762FNFJ-SEW-ACN	No change	TBD	Jun 30 th , 2016
55600AB	F-55600GNQJ-SLW-ABN	TBA	TBD	Jun 30 th , 2016