

FAX:+81-3-4221-4951



PHONE:+81-3-4221-4950

ELNA CO., LTD.

KYOBASHI EAST BLDG. 9F, 2-7-19, KYOBASHI, CHUO-KU, TOKYO, 104-0031, JAPAN

UA-2608(1/4)
7. Jun. 2022

Product Change Notification

To :

We would like to inform you about our new part numbering system. Due to an increase of our product lineup and expansion of our business to the new market, there is concern that the available characters of describing the part numbers will run out if we continue to use the current numbering system.

1. Item

Please refer to the part number table on the next page.

2. Description of change

	Current	New
Endurance	No difference	
Category temperature range	No difference	
Electrical performance	No difference	
Mechanical performance	No difference	
Case size	No difference	
Marking	No difference	

3. Changed date


After your approval

2. Part number

No.	Current PN		New PN	
	Customer PN	ELNA PN	Customer PN	ELNA PN
1	-----	DB-5R5D104T	-----	RSCB11045R5G07014T
2	-----	DB-5R5D105T	-----	RSCB11055R5L08015T
3	-----	DB-5R5D155T	-----	RSCB11555R5L08015T
4	-----	DB-5R5D224T	-----	RSCB12245R5G07014T
5	-----	DB-5R5D334T	-----	RSCB13345R5G07014T
6	-----	DB-5R5D473T	-----	RSCB14735R5G07014T
7	-----	DB-5R5D474T	-----	RSCB14745R5L08015T
8	-----	DBJ-5R5D104T	-----	RSCBJ1045R5G07014T
9	-----	DBJ-5R5D105T	-----	RSCBJ1055R5L08015T
10	-----	DBJ-5R5D224T	-----	RSCBJ2245R5G07014T
11	-----	DBJ-5R5D334T	-----	RSCBJ3345R5G07014T
12	-----	DBJ-5R5D473T	-----	RSCBJ4735R5G07014T
13	-----	DBN-5R5D104T	-----	RSCBN1045R5G07014T
14	-----	DBN-5R5D105T	-----	RSCBN1055R5L08015T
15	-----	DBN-5R5D155T	-----	RSCBN1555R5L08015T
16	-----	DBN-5R5D224T	-----	RSCBN2245R5G07014T
17	-----	DBN-5R5D334T	-----	RSCBN3345R5G07014T
18	-----	DBN-5R5D473T	-----	RSCBN4735R5G07014T
19	-----	DBN-5R5D474T	-----	RSCBN4745R5L08015T
20	-----	DH-5R5D104T	-----	RSCH11045R5G09014T
21	-----	DH-5R5D105T	-----	RSCH11055R5L09015T
22	-----	DH-5R5D224T	-----	RSCH12245R5G09014T
23	-----	DH-5R5D473T	-----	RSCH14735R5G09014T
24	-----	DH-5R5D474T	-----	RSCH14745R5L09015T
25	-----	DH-5R5D474T-F36	-----	RSCH14745R5L09074T
26	-----	DH-5R5D684T	-----	RSCH16845R5L09015T
27	-----	DHC-5R5D105T	-----	RSCHC1055R5L09015T
28	-----	DHC-5R5D684T	-----	RSCHC6845R5L09015T
29	-----	DHL-5R5D104T	-----	RSCHL1045R5G09014T
30	-----	DHL-5R5D105T	-----	RSCHL1055R5L09015T
31	-----	DHL-5R5D224GT	-----	RSCHL2245R5G09014GT
32	-----	DHL-5R5D224T	-----	RSCHL2245R5G09014T
33	-----	DHL-5R5D473T	-----	RSCHL4735R5G09014T
34	-----	DHL-5R5D474T-F45	-----	RSCHL4745R5L09039T
35	-----	DS-2R5H204T614-H2L	-----	RSCS12042R5D01004T
36	-----	DS-2R5H224U-HL	-----	RSCS12242R5D02008U
37	-----	DSK-3R3E204T614-E	-----	RSCSK2043R3D01007T
38	-----	DSK-3R3E224U-E	-----	RSCSK2243R3D02007U
39	-----	DSK-3R3H204T614-H2L	-----	RSCSK2043R3D01004T
40	-----	DSK-3R3H224U-HL	-----	RSCSK2243R3D02008U
41	-----	DSK-3R3H334T-HL	-----	RSCSK3343R3D02008T
42	-----	DVL-5R5D104T-R5	-----	RSCVL1045R5G10012T
43	-----	DVL-5R5D224T-R5	-----	RSCVL2245R5G10012T
44	-----	DVL-5R5D473T-R5	-----	RSCVL4735R5G10012T
45	-----	DVN-5R5D104T-R5	-----	RSCVN1045R5G08012T
46	-----	DVN-5R5D224T-R5	-----	RSCVN2245R5G08012T
47	-----	DVN-5R5D473T-R5	-----	RSCVN4735R5G08012T
48	-----	DVS-3R6D104T-R5	-----	RSCVS1043R6G08012T
49	-----	DVS-3R6D224T-R5	-----	RSCVS2243R6G08012T
50	-----	DVS-3R6D334T-R5	-----	RSCVS3343R6G08012T

No.	Current PN		New PN	
	Customer PN	ELNA PN	Customer PN	ELNA PN
51	-----	DVS-3R6D473T-R5	-----	RSCVS4733R6G08012T
52	-----	DX-5R5H104U	-----	RSCX11045R5F05013U
53	-----	DX-5R5H224U	-----	RSCX12245R5F05013U
54	-----	DX-5R5H334U	-----	RSCX13345R5F05013U
55	-----	DX-5R5H473U	-----	RSCX14735R5F05013U
56	-----	DX-5R5V104U	-----	RSCX11045R5F13013U
57	-----	DX-5R5V105U	-----	RSCX11055R5K20013U
58	-----	DX-5R5V224U	-----	RSCX12245R5F13013U
59	-----	DX-5R5V334U	-----	RSCX13345R5F13013U
60	-----	DX-5R5V473U	-----	RSCX14735R5F13013U
61	-----	DX-5R5V474SU	-----	RSCX14745R5F13013SU
62	-----	DXJ-5R5H104U	-----	RSCXJ1045R5F05013U
63	-----	DXJ-5R5H334U	-----	RSCXJ3345R5F05013U
64	-----	DXJ-5R5V224U	-----	RSCXJ2245R5F13013U
65	-----	DXJ-5R5V334U	-----	RSCXJ3345R5F13013U
66	-----	DXS-3R6H224U	-----	RSCXS2243R6F05013U
67	-----	DXS-3R6V105U	-----	RSCXS1053R6K20013U
68	-----	DXS-3R6V224U	-----	RSCXS2243R6F13013U
69	-----	DZ-2R5D105G3T	-----	RSDZ11052R5E12300T
70	-----	DZ-2R5D105T	-----	RSDZ11052R5E22300T
71	-----	DZ-2R5D106H8T	-----	RSDZ11062R5F35300T
72	-----	DZ-2R5D335T	-----	RSDZ13352R5G23300T
73	-----	DZ-2R5D506T	-----	RSZ15062R5N40001T
74	-----	DZN-2R5D155H3T	-----	RSDZN1552R5F14300T
75	-----	DZN-2R5D206T	-----	RSDZN2062R5K40300T
76	-----	DZN-2R7D105G5T	-----	RSDZN1052R7E22300T
77	-----	HTK-25V102MIERTQ-R5	-----	RAHTK102M1TGL5005RT
78	-----	HTK-25V331MH10ETQ-R2	-----	RAHTK331M1TFH0002ET
79	-----	HTK-25V561MHC5E-R2	-----	RSHTK561M1TFK5002E
80	-----	HTK-63V101MHC5E-R2	-----	RSHTK101M4EFK5002E
81	-----	HTX-25V101MF80TQ-R2	-----	RAHTX101M1TDE7002T
82	-----	HTX-25V221MG10ZTQ-R2	-----	RAHTX221M1TEH0002ZT
83	-----	HTX-25V331MH10TQ-R2	-----	RAHTX331M1TFH0002T
84	-----	HTX-25V331MH10ZTQ-R2	-----	RAHTX331M1TFH0002ZT
85	-----	HV-35V220ME61E-R2	-----	RSHV1220M1GCC8002E
86	-----	HVK-25V101MF80E-R2	-----	RSHVK101M1TDE7002E
87	-----	HVK-25V561MHC5E-R2	-----	RSHVK561M1TFK5002E
88	-----	HVK-35V271MH10E-R2	-----	RSHVK271M1GFH0002E
89	-----	HVK-63V100MF61E-R2	-----	RSHVK100M4EDC8002E
90	-----	HVK-63V101MHC5E-R2	-----	RSHVK101M4EFK5002E
91	-----	HVK-63V220MF80ETQ-R2	-----	RAHVK220M4EDE7002ET
92	-----	R2B-100V470MI5#	-----	RSR2B470M1HG20300T
93	-----	RBD-25V100KE3#N	-----	RCRBD100K1TC11300T
94	-----	RC2-16V101MF1#-T58	-----	RSRC2101M1ED07119T
95	-----	RE3-25V222MI6#-T4	-----	RSRE3222M1TG25101T
96	-----	RE3-35V222MJ6#	-----	RSRE3222M1GJ25300T
97	-----	RJ3-63V101MH3#	-----	RSRJ3101M4EF12300T
98	-----	RJ4-400V220MI6#-T4	-----	RSRJ4220M4HG25101T
99	-----	RJH-100V101MI5#	-----	RSRJH101M1HG20300T
100	-----	RJH-25V222MI9#	-----	RSRJH222M1TG40300T

No.	Current PN		New PN	
	Customer PN	ELNA PN	Customer PN	ELNA PN
101	-----	RJH-35V121MG3#	-----	RSRJH121M1GE12300T
102	-----	RJH-35V221MG5#	-----	RSRJH221M1GE20300T
103	-----	RJH-50V101MH4#	-----	RSRJH101M1UF16300T
104	-----	RJH-50V221MH6#	-----	RSRJH221M1UF25300T
105	-----	RMD-35V331MG10TQ-R2	-----	RAVMD331M1GEH0002T
106	-----	ROB-100V101MI5#	-----	RSR0B101M1HG20300T
107	-----	ROB-100V471MK8#	-----	RSR0B471M1HK35300T
108	-----	ROB-25V101MG3#	-----	RSR0B101M1TE11300T
109	-----	RV2-10V100MU-R	-----	RSV2100M1LBC3001U
110	-----	RV2-10V101MU-R	-----	RSV2101M1LDC3001U
111	-----	RV2-35V4R7MU-R	-----	RSV24R7M1GBC3001U
112	-----	RV2-50V100MU-R	-----	RSV2100M1UDC3001U
113	-----	RV2-6V470MU-R	-----	RSV2470M1JCC3001U
114	-----	RV5-16V470ME55U-R2	-----	RSV5470M1ECC3002U
115	-----	RVB-50V330G10Y1UQ-R2	-----	RAVVB330M1UEH0002Y1U
116	-----	RVD-35V101MF80TQ-R2	-----	RAVVD101M1GDE7002T
117	-----	RVO-50VR47MD55P2U-R	-----	RSVV0R47M1UBC3001P2U
118	-----	RVO-50VR47MD55P2U-R2	-----	RSVV0R47M1UBC3002P2U
119	-----	RVS-10V100MD55U-R	-----	RSVVS100M1LBC3001U
120	-----	RVS-16V470MF55U-R2	-----	RSVVS470M1EDC3002U
121	-----	RVS-35V100ME55U-R	-----	RSVVS100M1GCC3001U
122	-----	RVS-50V010MD55U-R	-----	RSVVS010M1UBC3001U
123	-----	RVS-50V100MF55U-R	-----	RSVVS100M1UDC3001U
124	-----	RVS-50V4R7ME55U-R	-----	RSVVS4R7M1UCC3001U
125	-----	RVS-6V101MF55U-R	-----	RSVVS101M1JDC3001U
126	-----	RVS-6V220MD55U-R	-----	RSVVS220M1JBC3001U
127	-----	RVS-6V470ME55U-R	-----	RSVVS470M1JCC3001U
128	-----	RVT-35V100ME61U-R	-----	RSVVT100M1GCC8001U
129	-----	RVT-35V221MH10UQ-R	-----	RAVVT221M1GFH0001U
130	-----	RVT-35V470MF80TQ-R2	-----	RAVVT470M1GDE7002T
131	-----	RVZ-35V331HA5Y1UQ-R2	-----	RAVVZ331M1GFH5002Y1U
132	-----	RVZ-6V221MF61U-R2	-----	RSVVZ221M1JDC8002U



A. Oyama

Engineering & Development sec. engineer