

# **Product Change Notification**

## **TE Connectivity**

Product Change Notification: E-21-002561-C PCN Date: 07-MAY-21

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

**General Product Description:** 

SOCKET ASSY, 2-35mm, CRIMP

### **Description of Changes**

To increase the retention of the retaining spring on the socket, the inner diameter of the retaining spring and the outer diameter of the socket were both reduced for -4 and -5 to create a tighter fit between the spring and the socket and the height of the retention tines on the spring were increased accordingly to maintain the proper location of the tip of the retention tines with respect to the ledge in the housing that these tines make contact with. For -1 and -2, only the width of socket shoulder shown as dimension K in customer drawing is changed.

#### Reason for Cancellation:

There is no way to keep PCN and keep the part revision as original one when production drawing revision doesn't need to change

#### Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<u>193673-2</u>	NO						

### Part Number(s) being Modified:

Part	Part Discontinued per PCN	Customer	Customer Part	Alias Part	Substitute Part	Substitute Alias Part	Description Of
Number		Drawing	Number	Number(s)	Number	Number(s)	Difference
<u>193673-2</u>	NO						