

Product Obsolescence Memo

PRECISION POTENTIOMETERS



January 28, 2019

Bourns® Model 3751H-422-103L and 3751H-423-103L Precision Potentiometers to be Discontinued

In accordance with our ongoing product lifecycle management procedure and due to low volume demand, Bourns has transferred the Model 3751H-422-103L and 3751H-423-103L Precision Potentiometers to an End of Product Life status.

Two recommended replacement products are available for your consideration and testing. The replacement devices offer a maximum torque specification of 25 oz./in. Please contact the [Bourns team of Field Application Engineers](#) if you have any questions regarding the suggested replacement parts and your application requirements.

Products purchased during this End of Product Life transition period will be covered by Bourns' standard warranty. Last Time Buy orders for these products will be considered non-cancellable and non-refundable.

Obsolete Part Number	Recommended Replacement Part Number
3751H-422-103L	3751H-601-103L
3751H-423-103L	3751H-602-103L

Please plan for the following deadlines:

Last time buy date: **August 1, 2019**

Last time ship date: **January 31, 2020**

Should you have any questions or need additional information, please feel free to contact [Customer Service/Inside Sales](#).

SC1906