



## Product Change Notification

### PCN-TT-241-2017

Business Unit	Product Line Code	Type of Change	Action	Date of Issue
TT - Trabtech	CLA	Product Change Notification	Notify Distributors and Field	1/30/2017

The following Phoenix Contact products have been modified. Existing specifications will be met or exceeded. Please review and acknowledge this document and inform your personnel as needed.

#### Description for Product Change Notification


The thermal-magnetic versions of the CB product family (CB TM)'s production is going to move to Indonesia. To properly comply with requirements there, the marking on the side of the breakers will be modified to include the proper notation.

#### Stock Status

Can existing stock still be used?	Yes
Is mixture of stock acceptable?	Yes

#### Transaction Dates

Date modification goes into effect from Germany:	1/30/2017
Expected first shipment (from Phoenix Contact) of the modified products(s):	3/1/2017





Phoenix Contact Inc.  
P.O. BOX 4100  
Harrisburg, PA 17111-0100  
Phone: 717-944-1300  
Fax: 717-944-1625

## Product Change Notification

*Should you have any issues with the timeline or content of this product change, please contact Phoenix Contact using the information below. Customers should acknowledge receipt of the PCN within 30 days of delivery of the PCN; provided, however, that the failure to acknowledge receipt does not affect the product change or the effective date thereof.*

**Contact Info:**

Jessica Yeh  
jyeh@phoenixcon.com

Thank you,

---

Matt Hemphill

Product Marketing Manager - Trabtech



## Product Change Notification

Part #	Type Description
2800835	CB TM1 0.5A SFB P
2800836	CB TM1 1A SFB P
2800837	CB TM1 2A SFB P
2800838	CB TM1 3A SFB P
2800839	CB TM1 4A SFB P
2800840	CB TM1 5A SFB P
2800841	CB TM1 6A SFB P
2800842	CB TM1 8A SFB P
2800843	CB TM1 10A SFB P
2800844	CB TM1 12A SFB P
2800845	CB TM1 16A SFB P
2800846	CB TM1 0.5A M1 P
2800847	CB TM1 1A M1 P
2800848	CB TM1 2A M1 P
2800849	CB TM1 3A M1 P
2800850	CB TM1 4A M1 P
2800851	CB TM1 5A M1 P
2800852	CB TM1 6A M1 P
2800853	CB TM1 8A M1 P
2800854	CB TM1 10A M1 P
2800855	CB TM1 12A M1 P
2800856	CB TM1 16A M1 P
2800857	CB TM1 0.5A F1 P
2800858	CB TM1 1A F1 P
2800859	CB TM1 2A F1 P
2800860	CB TM1 3A F1 P
2800861	CB TM1 4A F1 P
2800862	CB TM1 5A F1 P
2800863	CB TM1 6A F1 P
2800864	CB TM1 8A F1 P
2800865	CB TM1 10A F1 P
2800866	CB TM1 12A F1 P
2800867	CB TM1 16A F1 P
2800868	CB TM2 0.5A SFB P
2800869	CB TM2 1A SFB P
2800870	CB TM2 2A SFB P
2800871	CB TM2 3A SFB P
2800872	CB TM2 4A SFB P
2800873	CB TM2 5A SFB P
2800874	CB TM2 6A SFB P
2800875	CB TM2 8A SFB P
2800876	CB TM2 10A SFB P
2800877	CB TM2 12A SFB P
2800878	CB TM2 16A SFB P
2800879	CB TM2 0.5A M1 P
2800880	CB TM2 1A M1 P
2800881	CB TM2 2A M1 P



Phoenix Contact Inc.  
P.O. BOX 4100  
Harrisburg, PA 17111-0100  
Phone: 717-944-1300  
Fax: 717-944-1625

## Product Change Notification

2800882	CB TM2 3A M1 P
2800883	CB TM2 4A M1 P
2800884	CB TM2 5A M1 P
2800885	CB TM2 6A M1 P
2800886	CB TM2 8A M1 P
2800887	CB TM2 10A M1 P
2800888	CB TM2 12A M1 P
2800889	CB TM2 16A M1 P
2800890	CB TM2 0.5A F1 P
2800891	CB TM2 1A F1 P
2800892	CB TM2 2A F1 P
2800893	CB TM2 3A F1 P
2800894	CB TM2 4A F1 P
2800895	CB TM2 5A F1 P
2800896	CB TM2 6A F1 P
2800897	CB TM2 8A F1 P
2800898	CB TM2 10A F1 P
2800899	CB TM2 12A F1 P
2800900	CB TM2 16A F1 P