

LINT FREE WIPES

Non-abrasive, 4"x4" Pad

Provides superior cleaning of fiber optic cleaning ferrules without risk of scratching or lint residue. Lint free, non-abrasive, 4"x4" pad used for cleaning optical surfaces, precision instruments, tools, and electronic equipment. Use with fiber optic cleaning solution. Lint Free dry wipes are made from a hydro-entangled, 45/55 cellulose/polyester blend, for optimum purity in a wipe. These wipes have excellent absorbency, and contamination entrapment, as well as high strength. Lint Free non-woven dry Wipes are ideal as a premium wipe for any fiber optic surface. 100 pieces per pack.



Features

- Provides superior cleaning of fiber optic ferrules
- Lint Free, non-abrasive pad
- excellent absorbency, and contamination entrapment, as well as high strength
- 4"x4" pad
- 100 pieces per pack

Specifications

Parameter	Value
Material	45%/55% cellulose/polyester blend
Size	4"x4" pad
Quantity	100 pieces per pack
Lint Free	Yes

Ordering Information

Part Number	Description
LFW-100	Lint free, non-abrasive, 4"x4" pad used for cleaning optical surfaces (100 pieces)