

Issue Date: September 18th, 2020

Dear Valued Customer,

This notice is to inform you of the obsolescence of items that you have purchased from Littelfuse.

Description of the Change:

- We will obsolete and no longer support production of 95410 and its retail version 95410-BX.

Reason for The Change:

- Littelfuse was recently notified that one of our suppliers is no longer able to manufacture a component necessary to continue production of these finished goods.
- These finished goods are very mature and have seen sharply declining volumes in recent years. As such, the investments required to re-tool and re-source the critical component are not supported by current and projected demand.

Effective Date of the Change:

- Due to the sudden nature of this interruption, this obsolescence is effective immediately.


What You Need to Do:

- We will do our best to fulfill existing orders in the order in which they were received with the remaining componentry stock available. We will not be able to support any additional orders or last time buys.
- Any future demand for these parts should be shifted to alternative, similar products. We will assist on identifying suggested replacements on a customer-by-customer, application-by-application basis, so please contact us with questions.

For any questions, please reach out to either your local Customer Service or Inside Sales Representative.

We appreciate your continued partnership and business.

Sincerely,



Zachary Naughton
Global Product Manager
Littelfuse Commercial Vehicle Products