



Product Change Notification

TE Connectivity

Product Change Notification: E-19-007788

PCN Date: 05-JUN-19

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
DEUTSCH DTMN, DTM Wedges, EEC Box Manufacturing Location Change

Description of Changes
The Industrial and Commercial Transportation business unit of TE Connectivity is transferring the production of the part numbers listed below from TE Hemet/CA-USA to TE Empalme/ Mexico. Shipping point will change from Ontario, CA, USA to Hermosillo, Mexico. These PNs are TE proprietary designs, therefore considered catalog/general market product. Tools that manufacture parts within this PCN are identified as "swing tool" and TE reserves the right in future to move tool to a TE ICT Manufacturing location and/or a TE externally approved supplier as needed. In case of subsequent transfer of swing tool, PCN will be sent to notify but will have a zero day wait period. PPAP and/or sample requests must be submitted within 14 days of PCN submission via ict-ppap-request@te.com or TE e-PPAP system. Submissions will not occur without request. If PPAP is requested, disposition response is required within 14 days of submit date or it will be considered approved.

Reason for Changes:
This change is necessary for alignment of overall manufacturing capacity and footprint to better meet our Customer's needs. IMPORTANT: The change will not impact fit, form or function.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	05-SEP-2019
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	05-SEP-2024

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
EEC-5X650A	NO						
EEC-5X650B	NO						
WM-12P	NO			"ZPF00000000131479", "WM-12P-MS", "WM-12P-M"			
WM-12S	NO			"ZPF00000000131480", "WM-12S-AS", "WM-12S-LS", "WM-12S-L"			
WM-2P	NO			"ZPF00000000131465", "WM-2P-AS"			
WM-2PA	NO			"ZPF00000000131466"			
WM-2PB	NO			"ZPF00000000131467"			
WM-2S	NO			"ZPF00000000131468", "WM-2S-AS", "499003"			
WM-2SB	NO			"ZPF00000000131470"			
WM-3P	NO			"ZPF00000000131471", "8202608171", "4004200289", "19288-000"			
WM-3S	NO			"ZPF00000000131472", "WM-3S-AS", "8202609700"			
WM-4P	NO			"ZPF00000000113018", "ZPF00000000131473", "WM 4P", "8202609557"			
WM-4S	NO			"ZPF00000000113019", "ZPF00000000131474", "WM 4S", "8202606980", "4004200241"			
WM-6P	NO			"ZPF00000000131475"			
WM-6S	NO			"ZPF00000000131476", "2231457-1"			
WM-8P	NO			"ZPF00000000131477", "WM-8P-AS"			
WM-8S	NO			"ZPF00000000131478"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
EEC-5X650A	NO						
WM-12P	NO			"ZPF000000000131479", "WM-12P-MS", "WM-12P-M"			
WM-12S	NO			"ZPF000000000131480", "WM-12S-AS", "WM-12S-LS", "WM-12S-L"			
WM-2PA	NO			"ZPF000000000131466"			
WM-2S	NO			"ZPF000000000131468", "WM-2S-AS", "499003"			
WM-3P	NO			"ZPF000000000131471", "8202608171", "4004200289", "19288-000"			
WM-3S	NO			"ZPF000000000131472", "WM-3S-AS", "8202609700"			
WM-4P	NO			"ZPF000000000113018", "ZPF000000000131473", "WM 4P", "8202609557"			
WM-4S	NO			"ZPF000000000113019", "ZPF000000000131474", "WM 4S", "8202606980", "4004200241"			
WM-6P	NO			"ZPF000000000131475"			
WM-6S	NO			"ZPF000000000131476", "2231457-1"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
EEC-5X650A	NO						
WM-12P	NO			"ZPF000000000131479", "WM-12P-MS", "WM-12P-M"			
WM-12S	NO			"ZPF000000000131480", "WM-12S-AS", "WM-12S-LS", "WM-12S-L"			
WM-2PA	NO			"ZPF000000000131466"			
WM-2PB	NO			"ZPF000000000131467"			
WM-2SB	NO			"ZPF000000000131470"			
WM-3P	NO			"ZPF000000000131471", "8202608171", "4004200289", "19288-000"			
WM-3S	NO			"ZPF000000000131472", "WM-3S-AS", "8202609700"			
WM-4P	NO			"ZPF000000000113018", "ZPF000000000131473", "WM 4P", "8202609557"			
WM-4S	NO			"ZPF000000000113019", "ZPF000000000131474", "WM 4S", "8202606980", "4004200241"			
WM-6P	NO			"ZPF000000000131475"			
WM-6S	NO			"ZPF000000000131476", "2231457-1"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
EEC-5X650A	NO						
EEC-5X650B	NO						
WM-12P	NO			"ZPF000000000131479", "WM-12P-MS", "WM-12P-M"			
WM-12S	NO			"ZPF000000000131480", "WM-12S-AS", "WM-12S-LS", "WM-12S-L"			
WM-2P	NO			"ZPF000000000131465", "WM-2P-AS"			
WM-2PB	NO			"ZPF000000000131467"			
WM-2S	NO			"ZPF000000000131468", "WM-2S-AS", "499003"			
WM-2SB	NO			"ZPF000000000131470"			
WM-3P	NO			"ZPF000000000131471", "8202608171", "4004200289", "19288-000"			
WM-3S	NO			"ZPF000000000131472", "WM-3S-AS", "8202609700"			
WM-4P	NO			"ZPF000000000113018", "ZPF000000000131473", "WM 4P", "8202609557"			
WM-4S	NO			"ZPF000000000113019", "ZPF000000000131474", "WM 4S", "8202606980", "4004200241"			
WM-6P	NO			"ZPF000000000131475"			
WM-6S	NO			"ZPF000000000131476", "2231457-1"			
WM-8P	NO			"ZPF000000000131477", "WM-8P-AS"			
WM-8S	NO			"ZPF000000000131478"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
EEC-5X650A	NO						
EEC-5X650B	NO						
WM-12P	NO			"ZPF000000000131479", "WM-12P-MS", "WM-12P-M"			
WM-12S	NO			"ZPF000000000131480", "WM-12S-AS", "WM-12S-LS", "WM-12S-L"			
WM-2P	NO			"ZPF000000000131465", "WM-2P-AS"			
WM-2PB	NO			"ZPF000000000131467"			
WM-2S	NO			"ZPF000000000131468", "WM-2S-AS", "499003"			
WM-2SB	NO			"ZPF000000000131470"			
WM-3P	NO			"ZPF000000000131471", "8202608171", "4004200289", "19288-000"			
WM-3S	NO			"ZPF000000000131472", "WM-3S-AS", "8202609700"			
WM-4P	NO			"ZPF000000000113018", "ZPF000000000131473", "WM 4P", "8202609557"			
WM-4S	NO			"ZPF000000000113019", "ZPF000000000131474", "WM 4S", "8202606980", "4004200241"			
WM-6P	NO			"ZPF000000000131475"			
WM-6S	NO			"ZPF000000000131476", "2231457-1"			
WM-8P	NO			"ZPF000000000131477", "WM-8P-AS"			
WM-8S	NO			"ZPF000000000131478"			

