





PCN - 10 145

Issue Date: November 12 2010

Product Name:	Smartcards		
	S08 series SIM connectors		
Product Manager:	Hiran Namboothiri		
Subject:	Product Change Notification		
Distribution:	Global		
Type of Change:	Product Design Change		
Change Description:	<p>In order to improve the contact stability (contact normal force) of card reader after high temperature reflow soldering, we have modified the cover as shown below.</p> <div style="display: flex; justify-content: space-around; align-items: center;"> <div style="text-align: center;">  <p>S08 connector cover before Modification</p> </div> <div style="text-align: center;">  <p>S08 connector cover after Modification</p> </div> <div style="border: 1px solid black; padding: 5px; font-size: small;"> Protusion feature added to improve the contact normal force </div> </div>		
Reason for Change:	A protrusion feature has been added on the cover in order to improve the contact stability (contact normal force) of card reader after high temperature reflow soldering.		
Affected Parts:	List attached		
Effective Date of Change:	February	12	2011
Last Time Buy Date:	N/A	N/A	N/A
Last Disty Return Date:	N/A	N/A	N/A
Datasheet Attached?	N/A		
Qual/Test Data Attached?	N/A		
Samples Availability Date:	November	12	2010
Available Alternatives?	N/A		
Questions?	<p>Contact your local FCI Representative, or</p> <p>HIRAN NAMBOOTHIRI Senior Engineer - Product Management Email - Hiran.Namboothiri@fci.com PH - +91- 484 - 6611580</p>		