



Product Change Notification

Dear Partner,

Ixxat appreciates your involvement and your long-term loyalty. We understand that staying updated on the current and future happenings is of vital importance to our joint success. To this end, we would like to inform you of the changing life cycle and schedule for the following product(s).

Part no	Description	Replacement	New Status
ASG1000-C	IXSG I/O	ASG2506-C	Obsolete
ASG1002-C	IXSG I/O+870	ASG2506-C	Obsolete
ASG1004-C	IXSG I/O+850	ASG2506-C	Obsolete
ASG1006-C	IXSG I/O+870+850	ASG2506-C	Obsolete
ASG1014-C	IXSG I/O+870+850+DNP3	no replacement	Obsolete
ASG1015-C	IXSG I/O+870+850+DNP3+3G	no replacement	Obsolete
ASG1024-C	IXSG I/O+DNP3+850+870+LTE EU	no replacement	Obsolete
ASG1025-C	IXSG I/O+DNP3+850+870+LTE NA	no replacement	Obsolete
ASG1103-C	IXSG M-Bus+870+3G	no replacement	Obsolete
ASG1200-C	IXSG MIO	ASG2506-C	Obsolete
ASG1206-C	IXSG MIO+850+870	ASG2506-C	Obsolete
ASG1220-C	IXSG MIO+850+870+LTEEU	ASG2520-C	Obsolete
ASG1221-C	IXSG MIO+850+870+LTENA	ASG2521-C	Obsolete
ASG1227-C	Ixxat MIO+850+LTEEU	ASG2520-C	Obsolete
ASG2000-C	IXSG SW	ASG2004-C	Obsolete
ASG2006-C	IXSG SW+870+850	ASG2506-C	Obsolete
ASG2012-C	IXSG SW+850+DNP3	no replacement	Obsolete
ASG2014-C	IXSG SW+870+850+DNP3	no replacement	Obsolete
ASG2106-C	IXSG Switch+EIP+850+870	ASG4006-C + AWB5001	Obsolete
ASG2120-C	IXSG Switch+EIP+850+870+LTEEU	ASG4006-C + AWB1500 + AWB5001	Obsolete
ASG2121-C	IXSG Switch+EIP+850+870+LTENA	ASG4006-C + AWB1502 + AWB5001	Obsolete
ASG2206-C	IXSG Switch+PIR+850+870	ASG4006-C + AWB5001	Obsolete
ASG2220-C	IXSG Switch+PIR+850+870+LTEEU	ASG4006-C + AWB1500 + AWB5001	Obsolete
ASG2221-C	IXSG Switch+PIR+850+870+LTENA	ASG4006-C + AWB1502 + AWB5001	Obsolete
ASG2500-C	IXSG Switch+MIO	ASG2506-C	Obsolete
ASG2506-C	IXSG Switch+MIO+850+870		Limited
ASG2520-C	IXSG SW+MIO+850+870+LTEEU		Limited
ASG2521-C	IXSG SW+MIO+850+870+LTENA		Limited
ASG2536-C	IXSG SW+MIO+850+870+WLAN	ASG2506-C + AWB2030	Obsolete
ASG3000-C	IXSG	ASG2004-C	Obsolete
ASG3002-C	IXSG+870	ASG2506-C	Obsolete
ASG3004-C	IXSG+850	ASG2004-C	Obsolete
ASG3006-C	IXSG+870+850	ASG2506-C	Obsolete
ASG3014-C	IXSG+870+850+DNP3	no replacement	Obsolete
ASG3015-C	IXSG+870+850+DNP3+3G	no replacement	Obsolete
ASG3020-C	IXSG+850+870+LTEEU	ASG2520-C	Obsolete
ASG3021-C	IXSG+850+870+LTENA	ASG2521-C	Obsolete
ASG3036-C	IXSG Core+850+870+WLAN	ASG2506-C + AWB2030	Obsolete
ASG3070-C	IXSG Core+LTEEU	ASG1027-C	Obsolete



ASG4000-C	IXSG PRT	ASG4006-C	Obsolete
ASG4002-C	IXSG PRT+870	ASG4006-C	Obsolete
ASG4004-C	IXSG PRT+850	ASG4006-C	Obsolete
ASG4006-C	IXSG PRT+870+850		Limited
ASG4014-C	IXSG PRT+870+850+DNP3	no replacement	Obsolete
ASG4015-C	IXSG PRT+870+850+DNP3+3G	no replacement	Obsolete
ASG4100-C	IXSG EIP	ASG4106-C	Obsolete
ASG4102-C	IXSG EIP+870	ASG4106-C	Obsolete
ASG4104-C	IXSG EIP+850	ASG4106-C	Obsolete
ASG4106-C	IXSG EIP+870+850		Limited
ASG4114-C	IXSG EIP+870+850+DNP3	no replacement	Obsolete
ASG4115-C	IXSG EIP+870+850+DNP3+3G	no replacement	Obsolete
ASG4200-C	IXSG DPV1	ASG4206-C	Obsolete
ASG4202-C	IXSG DPV1+870	ASG4206-C	Obsolete
ASG4204-C	IXSG DPV1+850	ASG4206-C	Obsolete
ASG4206-C	IXSG DPV1+870+850		Limited
ASG4214-C	IXSG DPV1+870+850+DNP3	no replacement	Obsolete
ASG4215-C	IXSG DPV1+870+850+DNP3+3G	no replacement	Obsolete
ASG4224-C	IXSG DPV1+850+870+DNP3+LT	no replacement	Obsolete

Key Milestones

October 31 st , 2022	<p>The above-mentioned products will enter in either Limited or Obsolete phase as stated in the table.</p> <p>No “Last Time Buy” will be offered for products moved to obsolete, please see recommended replacement.</p> <p>Products moved to Limited will remain available until further notice.</p> <p>Part numbers not mentioned here will remain active.</p>
---------------------------------	--

Reason for Change

New status, obsolete:

- Products with replacement listed, we have decided to focus our offering with fewer part numbers.
- Products without replacement listed, (DNP) our customers are mainly relying on other technologies.

New status, limited:

- Product in maintenance mode, please see our lifecycle policy for further details.

Description of Change

Lifecycle policy: <https://www.ixxat.com/technical-support/product-life-cycle>

For further information, please contact your local sales representative.

Freddy Dahlberg,
Product Manager EnergyCom