

# PRODUCT CHANGE NOTIFICATION

Product Category POWER CONNECTORS 20220329-1

Product Group POWER CONNECTORS GROUNDING AND STEEL

ISSUE DATE: 29-Mar-22

IMPACTED REGIONS:  NA  EMEA  LATAM  AP

REASON FOR CHANGE:  DISCONTINUATION  
 OTHER

**DESCRIPTION OF CHANGE: (Required)**

Panduit LIECA series metric lugs are being discontinued and will no longer be available and have no replacement.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

**DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:**

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date			
Old product discontinuation date*	2022	7	16

**\*Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit’s Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

<b>IMPACTED PART NUMBER(s)</b>	<b>Compatibility Type</b>
LIECA25-6-C	No Replacement
LIECA25-8-C	No Replacement
LIECA25-10-C	No Replacement
LIECA35-6-C	No Replacement
LIECA35-8-C	No Replacement
LIECA35-10-C	No Replacement
LIECA35-12-C	No Replacement
LIECA50-6-L	No Replacement
LIECA50-8-L	No Replacement
LIECA50-10-L	No Replacement
LIECA50-12-L	No Replacement
LIECA70-8-L	No Replacement
LIECA70-10-L	No Replacement
LIECA70-12-L	No Replacement
LIECA95-8-L	No Replacement
LIECA95-10-L	No Replacement
LIECA95-12-L	No Replacement
LIECA120-8-L	No Replacement
LIECA120-10-L	No Replacement
LIECA120-12-L	No Replacement
LIECA150-10-X	No Replacement
LIECA150-12-X	No Replacement
LIECA185-10-X	No Replacement
LIECA185-12-X	No Replacement
LIECA240-10-X	No Replacement
LIECA240-12-X	No Replacement