



Product Change Notification

TE Connectivity

Product Change Notification: E-18-004604

PCN Date: 27-MAR-18

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
AMP TOOLING GPL B81

Description of Changes
OBSOLETE PART WITHOUT REPLACEMENT The following part numbers are being obsoleted (obsolete status) and no longer available. Please consult with your local customer sales representative for further details.

Reason for Changes:
Discontinuance. Dear Customer, You are receiving this notice because TE Connectivity has record of you purchasing a part or multiple parts on the list below. Within our continued efforts to manage/ optimize our product portfolio throughout the lifecycle, we've made the decision to obsolete the parts stated thereafter.

Estimated Dates:

Last Order Date (Obsolete Parts Only): 30-MAR-2018	First Date To Ship (Changed Parts Only):
Last Ship Date (Obsolete Parts Only): 30-APR-2018	Last Date for Mixed Shipments: (Changed Parts Only): No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
543464-1	YES						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
543464-1	YES						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
543464-1	YES						