

PRODUCT CHANGE NOTIFICATION

Product Category COMPUTER PRINTABLES 20230221-1

Product Group ID AND SAFETY

ISSUE DATE: 21-Feb-23

IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Required)

Part numbers M200X050AIT and M200X100AIT are being discontinued with replacements. Thanks for your ongoing support.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2023	2	21
Old product discontinuation date*	2023	2	22

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit’s Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

IMPACTED PART NUMBER(s)	Compatibility Type	Replacement Part 1	Replacement Part 2
M200X050AIT	Compatible	M300X050AIT	M200X050Y7T
M200X100AIT	Compatible	M300X100AIT	M200X100Y7T