



July 31, 2017

Change Notification for 155-31202 to 156-01516

To Our Valued Customer:

To better serve your business, we inform you of the following change.

HellermannTyton part number 155-31202 is no longer available. It is replaced by HellermannTyton part number 156-01516. The difference in these two items is:

Was made in Germany - Now made in USA assembled in Mexico.

Our records show that your part number is 1436-1061-ND and the last order was placed in 2015. We ask that future purchase orders be placed for the new HellermannTyton part number. Any open orders will be revised to the new part number.

Due to the urgency of this change, we ask that you acknowledge this notification within 10 business days. If we do not receive a response, we assume the change can be executed as planned without further notice. For additional information or assistance please contact your HellermannTyton Customer Service Representative.

We appreciate your support in this change and thank you for your continued business.

Sincerely,

Kelsey Shrader
Quality Project Engineer